

9  
*Central File*

August 26, 1980  
AUG 29 12:00

FILE: NG-3513(R)

SERIAL: NO-80-1231

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, GA 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2

DOCKET NO. 50-261

LICENSE NO. DPR-23

RESPONSE TO IE BULLETIN 80-19 - MERCURY-WETTED MATRIX RELAYS

Dear Mr. O'Reilly:

A review of the H. B. Robinson Unit No. 2 Reactor Protection Relay Logic and Safeguards Relay Logic has confirmed that mercury-wetted relays are not used in these systems.

If you have any questions concerning this information, please contact me or a member of my staff.

Yours very truly,

*Wary for B.J. Furr*

B. J. Furr  
Vice President  
Nuclear Operations

MVP:CSB:tma\*

cc: Mr. N. C. Moseley