

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9102060270 DOC. DATE: 91/01/30 NOTARIZED: NO DOCKET #
 FACIL: 50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261
 AUTH. NAME AUTHOR AFFILIATION
 FLOYD, S.D. Carolina Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards "Study Rept for Robinson Nuclear Plant Buried Svc
 Water Piping, Corrosion Issue," per 901217 telcon.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+250
 TITLE: OR Submittal: General Distribution

NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD2-1 LA	1 1	PD2-1 PD	1 1
LO, R	2 2		
INTERNAL: NRR/DET/ECMB 9H	1 1	NRR/DET/ESGB	1 1
NRR/DOEA/OTSB11	1 1	NRR/DST 8E2	1 1
NRR/DST/SELB 8D	1 1	NRR/DST/SICB 7E	1 1
NRR/DST/SRXB 8E	1 1	NUDOCS-ABSTRACT	1 1
OC/LFMB	1 0	OGC/HDS2	1 0
REG FILE 01	1 1	RES/DSIR/EIB	1 1
EXTERNAL: NRC PDR	1 1	NSIC	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 18 ENCL 16

M/A-2
ent



Carolina Power & Light Company

SERIAL: NLS-91-019

JAN 30 1991

United States Nuclear Regulatory Commission
ATTENTION: Document Control Desk
Washington, DC 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261/LICENSE NO. DPR-23
BURIED SERVICE WATER SYSTEM PIPE EVALUATION

Gentlemen:

On December 17, 1990, Carolina Power & Light Company (CP&L) and NRC held a telephone conference call to discuss issues associated with the Service Water System buried piping at H. B. Robinson Steam Electric Plant, Unit No. 2 (HBR2). The technical issues and questions raised by the NRC related to the piping wall condition, program approach, and repairs in progress were satisfactorily addressed. However, NRC requested that CP&L submit, prior to January 31, 1991, a study discussing the findings during the outage and the requirements and basis for long-term resolution of the corrosion issue. The study report, attached, concludes that actions taken return the subject pipe to long-term code compliance in accordance with Code Case N-480 and Generic Letter 90-05. Please note that the attached report contains certain information which was provided to NRC in our January 2, 1991 letter regarding this issue.

Please refer any questions regarding submittal to Mr. R. W. Prunty at (919) 546-7318.

Yours very truly,

S. D. Floyd
Manager

Nuclear Licensing Section

JSK/jbw (969RNP)

Attachment

cc: Mr. S. D. Ebnetter
Mr. L. Garner (NRC-HBR)
Mr. R. Lo

411 Fayetteville Street • P. O. Box 1551 • Raleigh, N. C. 27602

9102060270 910130
PDR ADDOCK 05000261
P PDR

Aool
11