

REGULATORY DOCKET FILE COPY

December 8, 1980

Control L.C.
DEC 16 PM 3:39
U.S. NRC
REGISTRATION SERVICES
BRANCH
DISTRIBUTION
SERVICES UNIT

FILE: NG-3513 (R)

SERIAL: NO-80-1772

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, GA 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
RESPONSE TO IE BULLETIN 80-23


Dear Mr. O'Reilly:

In response to your letter of November 14, 1980, transmitting IE Bulletin 80-23, Carolina Power & Light Company submits the following response for the H. B. Robinson Plant, Unit No. 2.

A thorough review has determined that neither solenoid valves nor solenoid valve parts manufactured by Valcor Engineering Corporation are in use at the Robinson Plant. The manpower expended for this review and for the required report preparation was 30 hours.

We trust that this satisfies the requirements of IE Bulletin 80-23.

Yours very truly,



B. J. Furr
Vice President
Nuclear Operations

SHC:ejj*

cc: Mr. Norman C. Moseley

Q

8012310404