

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH September

DOCKET NO. 050-0261
 UNIT NAME H.B. Robinson
 DATE 10/4/88
 COMPLETED BY V.F. Haynesworth
 TELEPHONE (803) 383-4524

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report #	System Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
0901	880922	F	42.37	A	1	88-021	SD	VALVEX	The unit was taken to Hot Shutdown due to excessive Penetration Pressurization System (PPS) leakage on Containment outlet purge valves. Seals to each of the valves were repaired, PPS was restored, and the unit was returned to service.

1
 F: Forced
 S: Scheduled

2
 Reason:
 A-Equipment Failure (Explain)
 B-Maintenance or Test
 C-Refueling
 D-Regulatory Restriction
 E-Operator Training & License Examination
 F-Administrative
 G-Operational Error (Explain)
 H-Other (Explain)

3
 Method:
 1-Manual
 2-Manual Scram.
 3-Automatic Scram.
 4-Other (Explain)

4
 Exhibit C - Instructions
 for Preparation of Data
 Entry Sheets for Licensee
 Event Report (LER) File (NUREG-
 0161)

5
 Exhibit I - Same Source

(9/77)

890130
 PDR ADOCK 05000261
 PDC

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH September

DOCKET NO. 050-0261
UNIT NAME H.B. Robinson
DATE 10/4/88
COMPLETED BY V.E. Haynesworth
TELEPHONE (803) 383-4524

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report #	System Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
0902	880927	F	---	A	1	-----	CH	PUMPXX	Power was reduced to 48% due to loss of "A" Main Feed Pump which automatically shut down upon sudden loss of bearing oil pressure. The system was found to have debris lodged in the Lube Oil Pump Discharge Relief Valve Seat. No apparent bearing damage resulted from the loss of oil pressure. Maintenance was completed, "A" Main Feed Pump returned to service and the unit returned to full power.

¹
F: Forced
S: Scheduled

²
Reason:
A-Equipment Failure (Explain)
B-Maintenance or Test
C-Refueling
D-Regulatory Restriction
E-Operator Training & License Examination
F-Administrative
G-Operational Error (Explain)
H-Other (Explain)

³
Method:
1-Manual
2-Manual Scram.
3-Automatic Scram.
4-Other (Explain)

⁴
Exhibit C - Instructions
for Preparation of Data
Entry Sheets for Licensee
Event Report (LER) File (NUREG-
0161)

⁵
Exhibit I - Same Source