

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 050-0261
UNIT NAME H. B. Robinson
DATE 08/03/90
COMPLETED BY J. B. Woods
TELEPHONE (803) 383-4524

REPORT MONTH July

| No. | Date | Type ¹ | Duration (Hours) | Reason ² | Method of Shutting Down Reactor ³ | Licensee Event Report # | System Code ⁴ | Component Code ⁵ | Cause & Corrective Action to Prevent Recurrence |
|------|--------|-------------------|---------------------|---------------------|--|-------------------------------|-----------------------------|--------------------------------|--|
| 0701 | 900720 | F | 2.72 | B | 1 | | CC | Valvex | Cause: Ramp down to 60% reactor power to perform OST-551 and repair steam valve, MS-78. Corrective Action: Return to full power after completion of OST-551, Monthly Turbine Valve Test, and repair of MS-78. |

1
F: Forced
S: Scheduled

2
Reason:
A-Equipment Failure (Explain)
B-Maintenance or Test
C-Refueling
D-Regulatory Restriction
E-Operator Training & License Examination
F-Administrative
G-Operational Error (Explain)
H-Other (Explain)

3
Method:
1-Manual
2-Manual Scram.
3-Automatic Scram.
4-Other (Explain)

4
Exhibit G - Instructions
for Preparation of Data
Entry Sheets for Licensee
Event Report (LER) File (NUREG-
0161)

5
Exhibit I - Same Source

(9/77)

9009170095 900910
FDR ADUCK 05000261
PDC