

- d. At least two licensed operators shall be present in the control room during reactor start-up, scheduled reactor shutdown, and during recovery from reactor trips.
- e. An individual qualified in radiation protection procedures shall be on site when fuel is in the reactor.
- f. ALL CORE ALTERATIONS after the initial fuel loading shall be directly supervised by either a licensed Senior Reactor Operator or Senior Reactor Operator limited to fuel handling who has no other concurrent responsibilities during this operation.
- g. A plant fire brigade of at least five members shall be maintained on site at all times. This excludes three members of the minimum shift crew necessary for safe shutdown of the plant and any personnel required for other essential functions during a fire emergency.
- h. The shift complement may be one less than the minimum requirement of Section 6.2.3.a and 6.2.3.b for a period of time not to exceed 2 hours in order to accommodate unexpected absence of on-duty shift members provided immediate action is taken to restore the shift complement to within the minimum requirements of Section 6.2.3.a and 6.2.3.b. This provision does not permit any shift member position to be unmanned upon shift change due to an oncoming shift member being late or absent.

Fire brigade may be one less than the minimum requirement of Section 6.2.3.g for a period of time not to exceed 2 hours, in order to accommodate unexpected absence, provided immediate action is taken to fill the required positions.

509030460 850828
DR ADDCK 05000261
P PDR