

ENCLOSURE 1  
REVISED PAGES

8609120062 860903  
PDR ADOCK 05000261  
P PDR

(0908NEL)

## 6.2 ORGANIZATION

### Offsite

6.2.1 The offsite organization for facility management and technical support shall be as shown on Figure 6.2-1.

### 6.2.2 Definitions

- a) Personnel reporting to the General Manager - Robinson Plant shall be identified in Section 6 of the Technical Specifications as the plant staff.
- b) Personnel reporting to the Manager - Control and Administration shall be identified in Section 6 of the Technical Specifications as the C&A staff.

### Facility Staff

6.2.3 The Robinson Nuclear Project organization shall be as shown in Figure 6.2-2 and:

- a) The shift complement during hot operations shall consist of at least one Shift Foreman holding a Senior Reactor Operator's License, one Senior Control Operator holding a Senior Reactor Operator's License, two Control Operators each holding a Reactor Operator's License, two additional shift members, and one Shift Technical Advisor. If an individual that holds a Senior Reactor Operator's License also meets the Shift Technical Advisor requirements, that individual may act in both capacities. The limitations on the use of overtime applies to the HBR2 Shift Foremen, Senior-Control Operators, Control Operators, and Shift Engineers. These limitations apply only when HBR2 Reactor Coolant System is greater than 200 F or when fuel is being moved within the Reactor Pressure Vessel. These limitations may be applied to other key "safety" personnel as warranted by the

plant conditions and other circumstances at the discretion of the Plant General Manager.

CP&L's overtime policy is summarized as follows:

- 1) An individual shall not be permitted to work more than 12 hours straight (not including shift turnover time).
- 2) An individual will have at least the same number of hours off between work periods as the length of his last work period (not including shift turnover time).
- 3) An individual shall not work more than 84 hours in any 7 day period (not including shift turnover time).
- 4) An individual shall not work more than 14 consecutive days without having two consecutive days off.

Under very unusual circumstances, deviations from above restrictions may be authorized by the Plant General Manager. When the overtime required exceeds the limitations described above, the circumstances must be documented.

- b) The shift complement during cold shutdown shall consist of at least one Shift Foreman holding a Senior Reactor Operator's License, one Control Operator holding a Reactor Operator's License and one additional shift member.
- c) At least one licensed Operator shall be in the control room when fuel is in the reactor.