

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8011120437 DOC. DATE: 80/11/05 NOTARIZED: NO DOCKET # 05000261
 FACIL: 50-261 H. B. Robinson Plant, Unit 2, Carolina Power and Light 05000325
 50-325 Brunswick Steam Electric Plant, Unit 1, Carolina Power 05000324
 50-324 Brunswick Steam Electric Plant, Unit 2, Carolina Power
 AUTH. NAME UTLEY, E.E. AUTHOR AFFILIATION Carolina Power & Light Co.
 RECIP. NAME EISENHUT, D.G. RECIPIENT AFFILIATION Division of Licensing

SUBJECT: Submits info re shift staffing in response to NRC 800731 ltr transmitting interim criteria.

DISTRIBUTION CODE: A001S COPIES RECEIVED: LTR 1 ENCL 2 SIZE: 1
 TITLE: General Distribution for after Issuance of Operating License

NOTES:

	RECIPIENT ID CODE/NAME		COPIES LTR ENCL		RECIPIENT ID CODE/NAME		COPIES LTR ENCL
ACTION:	VARGA, S.	04	13		IPPOLITO, T.	04	13
INTERNAL:	D/DIR, HUM	FAC08	1		I&E	06	2
	NRC PDR	02	1		OELD	11	1
	OR ASSESS BR	10	1		REG FILE	01	1
EXTERNAL:	ACRS	09	16		LPDR	03	1
	NSIC	05	1				

NOV 13 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR 51 ENCL 4



Carolina Power & Light Company

November 5, 1980

File: NG-3514(B&R)

Serial No.: NO-80-1648

Mr. Darrell G. Eisenhut, Director
Division of Licensing
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

H. B. ROBINSON STEAM ELECTRIC PLANT UNIT NO. 2
DOCKET 50-261, LICENSE NO. DPR-23
BRUNSWICK STEAM ELECTRIC PLANT UNIT NOS. 1 AND 2
DOCKET 50-325 AND 324, LICENSE NOS. DPR-71 AND 62
INTERIM CRITERIA FOR SHIFT STAFFING

US NRC
DISTRIBUTION SERVICES
BRANCH

1980 NOV 10 AM 10 56

RECEIVED DISTRIBUTION
SERVICES UNIT

Dear Mr. Eisenhut:

We have reviewed your July 31, 1980 letter transmitting interim criteria for shift staffing and have assessed the compliance of each of our operating units to these criteria. The response of each plant is summarized below.

H. B. Robinson

The Robinson Plant is not now in conformance with the interim guidelines for all shifts. While each shift always has the required total number of licensed personnel, on some shifts this complement is composed of a shift supervisor with an SRO and three ROs instead of the guideline staffing of two SROs and two ROs. Efforts are underway to alleviate this shortage of SROs, but because of the uncertainty of the criteria for qualification to take SRO examinations, CP&L believes it may not be able to reach full compliance with these interim guidelines at Robinson prior to July 1, 1982. CP&L is committed to achieving compliance with the guidelines as quickly as possible.

Brunswick

The Brunswick Plant is currently operating in full compliance with the interim guidelines and plans to continue to do so.

Yours very truly,

E. E. Utley

Executive Vice President
Power Supply and
Engineering & Construction

CSB/jc (068-515)

cc: Mr. T. A. Ippolito
Mr. Steven A. Varga

A001
S/10

8011120437

411 Fayetteville Street • P. O. Box 1551 • Raleigh, N. C. 27602