

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8105260385 DOC. DATE: 81/05/19 NOTARIZED: NO DOCKET #  
 FACIL: 50-261 H. B. Robinson Plant, Unit 2, Carolina Power and Light 05000261  
 AUTH. NAME: UTLEY, E. E. AUTHOR AFFILIATION: Carolina Power & Light Co.  
 RECIP. NAME: EISENHUT, D. G. RECIPIENT AFFILIATION: Division of Licensing

SUBJECT: Advises that interim actions requested in NRC 801222 ltr re control of heavy loads will not be completed until 810605 for Unit 2. Requests for addl info will be submitted on 810622 & 0922 as scheduled.

DISTRIBUTION CODE: A001S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: General Distribution for after Issuance of Operating License

## NOTES:

	RECIPIENT ID CODE/NAME		COPIES			RECIPIENT ID CODE/NAME		COPIES	
			LTTR	ENCL				LTTR	ENCL
ACTION:	VARGA, S.	04	13	15					
INTERNAL:	D/DIR, HUM FAC08		1	1		DIR, DIV OF LIC		1	1
	I&E	06	2	2		NRC PDR	02	1	1
	OELD	11	1	0		OR ASSESS BR	10	1	0
	RAD ASMT BR		1	1		<u>REG FILE</u>	01	1	1
EXTERNAL:	ACRS	09	16	16		LPDR	03	1	
	NSIC	05	1						

MAY 28 1981



Carolina Power & Light Company

May 19, 1981

File: NG-3514(R)

Serial No.: NO-81-876

Office of Nuclear Reactor Regulation  
Attention: Mr. Darrell G. Eisenhut, Director  
Division of Licensing  
United States Nuclear Regulatory Commission  
Washington, D. C. 20555



H. B. ROBINSON STEAM ELECTRIC PLANT UNIT NO. 2  
DOCKET NO. 50-261  
LICENSE NO. DPR-23  
CONTROL OF HEAVY LOADS AT NUCLEAR POWER PLANTS

Dear Mr. Varga:

By letter dated December 22, 1980, the NRC required that certain interim actions for the control of heavy loads be completed by May 15, 1981. Requests for additional information on this subject are due to the NRC on June 22, 1981 and September 22, 1981.

Carolina Power & Light Company (CP&L) has staffed a work group to respond to your concerns regarding the control of heavy loads at our Brunswick Steam Electric Plant, (BSEP) Units 1 and 2 and at H. B. Robinson Unit 2. Work on meeting the interim actions was scheduled to be completed at BSEP before H. B. Robinson. The BSEP plant will be in compliance by May 15, 1981. However, due to the imminent steam generator inspection outage, plant personnel resources are not available to meet with our work group in completing the interim actions at H. B. Robinson on schedule. CP&L has determined that we will not be able to complete the interim action until June 5, 1981 for H. B. Robinson Unit 2. We do anticipate being able to respond to the June 22, 1981 and September 22, 1981 requests for additional information on schedule.

Yours very truly,

E. E. Utley  
Executive Vice President  
Power Supply and  
Engineering & Construction

SDF/dk (N#56)

cc: Mr. J. D. Neighbors

A001  
3  
1/0

8105260385

P