

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8203090337 DOC. DATE: 82/03/01 NOTARIZED: NO DOCKET #  
 FACIL: 50-261 H. B. Robinson Plant, Unit 2, Carolina Power and Light 05000261  
 AUTH. NAME: AUTHOR AFFILIATION  
 HOWE, P.W. Carolina Power & Light Co.  
 RECIP. NAME: RECIPIENT AFFILIATION  
 VARGA, S.A. Operating Reactors Branch 1

SUBJECT: Notifies that 10CFR50 App R fire protection info will be submitted by 820310 to allow adequate time for technical & mgt review per preparation requirements for refueling & maint outage.

DISTRIBUTION CODE: A006S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: Fire Protection Information (After Issuance of OP. Lic.)

## NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
ACTION:	ORB #1 BC 01	7		
INTERNAL:	ELD	1	GC	1
	IE 06	2	NRR FIORAVANT07	2
	NRR WAMBACH 10	1	NRR/DE/CEB 08	3
	NRR/DL DIR	1	REG FILE 04	1
EXTERNAL:	ACRS 09	10	LPDR 03	1
	NRC PDR 02	1	NSIC 05	1
	NTIS	1		


TOTAL NUMBER OF COPIES REQUIRED: LTR 33 ENCL 0



Carolina Power & Light Company

March 1, 1982

Office of Nuclear Reactor Regulation  
ATTN: Mr. Steven A. Varga, Chief  
Operating Reactors Branch No. 1  
United States Nuclear Regulatory Commission  
Washington, D.C. 20555



H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2  
DOCKET NO. 50-261  
LICENSE NO. DPR-23  
10CFR50 APPENDIX R FIRE PROTECTION SUBMITTALS

Dear Mr. Varga:

In our letter of October 15, 1981, we requested an extension until March 1, 1982 to submit information concerning the compliance of H. B. Robinson Unit 2 Fire Protection Program with Appendix R, 10CFR50. In telephone conversations of February 26 and March 1, 1982, we discussed with the Robinson Project Manager the need to defer this submittal from March 1 until March 10, 1982. This additional time has become necessary due to the preparation requirements for the refueling and maintenance outage, which began February 26, 1982. This is a major outage, which includes the 10 year in-service inspection of the reactor vessel, and thus involves substantial plant and management resources. At the time that the March 1 submittal date was established, this refueling and maintenance outage was expected to begin on or after March 7, 1982, and would not have overlapped our scheduled Appendix R submittal. The earlier outage date developed because of the better than expected capacity factor under the  $T_{avg}$  program for the Robinson steam generators. Therefore, in order to allow adequate time for technical and management review of our submittal, we will submit our Appendix R information by March 10, 1982.

If you should have any questions, please contact our staff.

Yours very truly,

P. W. Howe  
Vice President  
Technical Services

DLB/lr (5384)

cc: Mr. J. P. O'Reilly (NRC-RII)

A006  
s  
1/0

8203090337 820301  
PDR ADOCK 05000261  
F PDR