

AEC CONTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 153

FILE:

FROM:
Carolina Power & Light Company
Hartsville, S.C.
Mr. B.J. Furr

DATE OF DOC
1-4-74

DATE REC'D
1-4-74

LTR

MEMO

RPT

OTHER

TELECOPY

TO:
J.F. O'Leary

ORIG
1

CC OTHER

SENT AEC PDR XXX
SENT LOCAL PDR XXX

CLASS

UNCLASS
XXX

PROP INFO

INPUT

NO CYS REC'D
1

DOCKET NO:
50-261

DESCRIPTION:

Telecopy reporting an abnormal occurrence at the
H.B. Robinson Unit #2 concern....Boron injection
~~above~~ the minimum concentration.....
Below

ENCLOSURES:

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: H.B. Robinson #2

FOR ACTION/INFORMATION 1-10-74 JB

BUTLER(L)	SCHWENCER(L)	ZIEMANN(L)	REGAN(E)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
CLARK(L)	STOLZ(L)	DICKER(E)	
W/ Copies	W/ Copies	W/ Copies	W/ Copies
GOLLER(L)	VASSALLO(L)	KNIGHTON(E)	
W/ Copies	W/ Copies	W/ Copies	W/ Copies
KNIEL(L)	✓SCHEMEL(L)	YOUNGBLOOD(E)	
W/ Copies	W/7 Copies	W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u>	<u>TECH REVIEW</u>	DENTON	<u>LIC ASST</u>	<u>A/T IND</u>
✓AEC PDR	✓HENDRIE	GRIMES		BRAITMAN
✓OGC, ROOM P-506A	SCHROEDER	GAMMILL	DIGGS (L)	SALTZMAN
✓MUNTZING/STAFF	✓MACCARY	KASTNER	GEARIN (L)	B. HURT
✓CASE	✓KNIGHT	BALLARD	GOULBOURNE (L)	<u>PLANS</u>
GIAMBUSO	✓PAWLICKI	SPANGLER	LEE (L)	MCDONALD
BOYD	✓SHAO		MAIGRET (L)	DUBE
MOORE (L)(BWR)	✓STELLO	<u>ENVIRO</u>	SERVICE (L)	<u>INFO</u>
DEYOUNG(L)(PWR)	✓HOUSTON	MULLER	SHEPPARD (E)	C. MILES
✓SKOVHOLT (L)	✓NOVAK	DICKER	SMITH (L)	✓B. King.
P. COLLINS	✓ROSS	KNIGHTON	✓TEETS (L)	
	✓IPPOLITO	YOUNGBLOOD	WADE (E)	
✓REG OPR	✓TEDESCO	REGAN	WILLIAMS (E)	
FILE & REGION(3)	✓LONG	PROJECT LDR	WILSON (L)	
✓MORRIS	✓LAINAS			
✓STEELE	✓BENAROYA	<u>HARLESS</u>		
	✓VOLLMER			

EXTERNAL DISTRIBUTION

✓1 - LOCAL PDR Hartsville, S.C.	(1)(2)(10)-NATIONAL LAB'S	1-PDR-SAN/LA/NY
✓1 - DTIE(ABERNATHY)	1-ASLBP(E/W Bldg, Rm 529)	1-GERALD LELLOUCHE
✓1 - NSIC(BUCHANAN)	1-W. PENNINGTON, Rm E-201 GT	BROOKHAVEN NAT. LAB
1 - ASLB(YORE/SAYRE/ WOODARD/"H" ST.	1-CONSULTANT'S	1-AGMED(Ruth Gussman)
✓16 - CYS ACRS HOLDING Sent to Teets	NEWMARK/BLUME/AGBABIAN	RM-B-127, GT.
1-10-74	1-GERALD ULRIKSON...ORNL	1-RD..MULLER..F-309 GT

CP&L

Carolina Power & Light Company


Record 114/114
Bethesda 9:37

50-261

Company Correspondence

H. B. ROBINSON STEAM ELECTRIC PLANT
Post Office Box 790
Hartsville, South Carolina


January 4, 1974



Robinson File No. 2-0-4-a

Mr. Norman C. Moseley, Director
U. S. Atomic Energy Commission
Directorate of Regulatory Operations
Region II - Suite 818
230 Peachtree Street, N. W.
Atlanta, Georgia 30303

Mr. John F. O'Leary
Directorate of Licensing (Office of Regulation)
U. S. Atomic Energy Commission
Washington, D. C. 20545



Dear Sirs:

In accordance with Section 6.6.2 of the Technical Specification the following is reported as a possible abnormal occurrence.

On January 3, 1974, routine sampling indicated the Boron Injection Tank Boron Concentration to be below the concentration required by Section 3.3.1.1 of the Technical Specifications. Preparations were initiated to place the Reactor in a hot shutdown condition, however, before load was reduced, subsequent sampling and analysis proved the Boron injection to be above the minimum Boron Concentration of 20,000 pps.

This was reported to Mr. Herb Whitener of DRO by telephone on January 4, 1974.

Yours very truly,

B. J. Furr
Barry J. Furr, Manager
H. B. Robinson SEG Plant

JBM:rbs