

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 1037

FILE: _____

FROM: Carolina Power & Light Company Hartsville, South Carolina Benny J. Furr			DATE OF DOC 2-6-74	DATE REC'D 2-7-74	LTR	MEMO	RPT	OTHER Facsimile
TO: Mr. John O'Leary			ORIG 1	CC	OTHER	SENT AEC PDR X SENT LOCAL PDR y		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-261		

DESCRIPTION:
Facsimile reporting an Abnormal Occurrence on 2-6-74, in which the indicating lights on the RTGB, were found not illuminated.....

ENCLOSURES:

Do Not Remove
ACKNOWLEDGED

PLANT NAME: H. B. Robinson

FOR ACTION/INFORMATION

2-7-74

AB

BUTLER(L) W/ Copies	SCHWENCER(L) W/ Copies	ZIEMANN(L) W/ Copies	REGAN(E) W/ Copies
CLARK(L) W/ Copies	STOLZ(L) W/ Copies	DICKER(E) W/ Copies	W/ Copies
GOLLER(L) W/ Copies	VASSALLO(L) W/ Copies	KNIGHTON(E) W/ Copies	W/ Copies
KNIEL(L) W/ Copies	✓ SCHEMEL(L) W/ 7 Copies	YOUNGBLOOD(E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

✓ <u>REG FILE</u>	<u>TECH REVIEW</u>	DENTON	<u>LIC ASST</u>	<u>A/T IND</u>
✓ AEC PDR	✓ HENDRIE	GRIMES		BRAITMAN
✓ OGC, ROOM P-506A	✓ SCHROEDER	GAMMILL	DIGGS (L)	SALTZMAN
✓ MUNTZING/STAFF	✓ MACCARY	KASTNER	GEARIN (L)	B. HURT
✓ CASE	✓ KNIGHT	BALLARD	GOULBOURNE (L)	<u>PLANS</u>
GIAMBUSSO	✓ PAWLICKI	SPANGLER	LEE (L)	MCDONALD
BOYD	✓ SHAO		MAIGRET (L)	DUBE w/Input
MOORE (L) (BWR)	✓ STELLO	<u>ENVIRO</u>	SERVICE (L)	<u>INFO</u>
DEYOUNG (L) (PWR)	✓ HOUSTON	MULLER	SHEPPARD (E)	C. MILES
✓ SKOVHOLT (L)	✓ NOVAK	DICKER	SMITH (L)	✓ B. KING
P. COLLINS	✓ ROSS	KNIGHTON	✓ TEETS (L)	
DENISE	✓ IPPOLITO	YOUNGBLOOD	WADE (E)	
<u>REG OPR</u>	✓ TEDESCO	REGAN	WILLIAMS (E)	
✓ FILE & REGION(3)	✓ LONG	PROJECT LDR	WILSON (L)	
✓ MORRIS	✓ LAINAS		S. REED (L)	
✓ STEELE	✓ BENAROYA	<u>HARLESS</u>		
	✓ VOLLMER			

EXTERNAL DISTRIBUTION

✓ 1 - LOCAL PDR Hartville, S. C.	(1)(2)(10)-NATIONAL LAB'S	1-PDR-SAN/LA/NY
✓ 1 - DTIE(ABERNATHY)	1-ASLBP(E/W Bldg, Rm 529)	1-GERALD LELLOUCHE
✓ 1 - NSIC(BUCHANAN)	1-W. PENNINGTON, Rm E-201 GT	BROOKHAVEN NAT. LAB
1 - ASLB(YORE/SAYRE/	1-CONSULTANT'S	1-AGMED(Ruth Gussman)
WOODARD/"H" ST.	NEWMARK/BLUME/AGBABIAN	RM-B-127, GT.
✓ 16 - CYS ACRS HOLDING SENT TO LIC ASST.	1-GERALD ULRIKSON...ORNL	1-RD..MULLER..F-309 GT
S. TEETS ON 2-7-74		

Regulatory

File Cy.

CP&L

Carolina Power & Light Company

Rec'd BETH
4:50 pm

H. B. ROBINSON STEAM ELECTRIC PLANT
Post Office Box 790
Hartsville, South Carolina

50-261

February 6, 1974

Robinson File No. 2-0-4-a

Mr. Norman C. Moseley, Director
U. S. Atomic Energy Commission
Directorate of Regulatory Operations
Region II - Suite 818
230 Peachtree Street, N. W.
Atlanta, Georgia 30303

Mr. John F. O'Leary
Directorate of Licensing (Office of Regulation)
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Sirs:

In accordance with section 6.6.2 of the Technical Specifications the following abnormal occurrence is reported.

On February 6, 1974, at 0847 hours the indicating lights on the RTGB for fan cooler Unit No. 1 were found not illuminated. Investigation revealed that the unit was inoperable due to the control power fuses being blown as a result of a short circuit in the indicating lights on a remote control panel for this unit. Repairs were made and the unit declared operable at 1145 hours.


This was reported to Mr. Herb Whitener of AEC DRO by telephone on February 6, 1974.

Yours very truly,

Benny J. Furr (JBFm)

Benny J. Furr, Manager
H. B. Robinson SEG Plant

JEM:rb



1037