

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL  
(TEMPORARY FORM)

CONTROL NO: 1046

FILE: \_\_\_\_\_

FROM: Carolina Power & Light Company Hartsville, South Carolina Mr. B.J. Furr			DATE OF DOC 2-7-74	DATE REC'D 2-7-74	LTR	MEMO	RPT	OTHER facimile
TO: J.F. O'Leary			ORIG 1	CC	OTHER	SENT AEC PDR XXX SENT LOCAL PDR XXX		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-261			

DESCRIPTION:  
Facimile reporting an abnormal occurrence at the H.B. Robinson Nuclear facility concern.... the outer door to the personnel air lock was not locked as required by the tech specs....

ENCLOSURES:

**ACKNOWLEDGED**

**DO NOT REMOVE**

PLANT NAME: H.B. Robinson

FOR ACTION/INFORMATION 2-11-74 JB

BUTLER(L) W/ Copies	SCHWENCER(L) W/ Copies	ZIEMANN(L) W/ Copies	REGAN(E) W/ Copies
CLARK(L) W/ Copies	STOLZ(L) W/ Copies	DICKER(E) W/ Copies	W/ Copies
GOLLER(L) W/ Copies	VASSALLO(L) W/ Copies	KNIGHTON(E) W/ Copies	W/ Copies
KNIEL(L) W/ Copies	✓ SCHEMEL(L) W/ Copies	YOUNGBLOOD(E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

✓ REG FILE	TECH REVIEW	DENTON	LIC ASST	A/T IND
✓ AEC PDR	✓ HENDRIE	GRIMES		BRAITMAN
✓ OGC, ROOM P-506A	SCHROEDER	GAMMILL	DIGGS (L)	SALTZMAN
✓ MUNTZING/STAFF	✓ MACCARY	KASTNER	GEARIN (L)	B. HURT
✓ CASE	✓ KNIGHT	BALLARD	GOULBOURNE (L)	PLANS
GIAMBUSO	✓ PAWLICKI	SPANGLER	LEE (L)	MCDONALD
BOYD	✓ SHAO		MAIGRET (L)	DUBE w/Input
MOORE (L)(BWR)	✓ STELLO	ENVIRO	SERVICE (L)	INFO
DEYOUNG(L)(PWR)	✓ HOUSTON	MULLER	SHEPPARD (E)	C. MILES
✓ SKOVHOLT (L)	✓ NOVAK	DICKER	SMITH (L)	✓ B. KING
P. COLLINS	✓ ROSS	KNIGHTON	✓ TEETS (L)	
DENISE	✓ IPPOLITO	YOUNGBLOOD	WADE (E)	
✓ REG OPR	✓ TEDESCO	REGAN	WILLIAMS (E)	
FILE & REGION(3)	✓ LONG	PROJECT LDR	WILSON (L)	
✓ MORRIS	✓ LAINAS		S. REED (L)	
✓ STEELE	✓ BENAROYA	HARLESS		
	✓ VOLLMER			

EXTERNAL DISTRIBUTION

✓ 1 - LOCAL PDR Hartsville, S.C.	(1)(2)(10)-NATIONAL LAB'S	1-PDR-SAN/LA/NY
✓ 1 - DTIE(ABERNATHY)	1-ASLBP(E/W Bldg, Rm 529)	1-GERALD LELLOUCHE
✓ 1 - NSIC(BUCHANAN)	1-W. PENNINGTON, Rm E-201 GT	BROOKHAVEN NAT. LAB
1 - ASLB(YORE/SAYRE/ WOODARD/"H" ST.	1-CONSULTANT'S	1-AGMED(Ruth Gussman)
✓ 16 - CYS ACRS XXXXXXXX Sent to Teets	NEWMARK/BLUME/AGBABIAN	RM-B-127, GT.
2-11-74	1-GERALD ULRIKSON...ORNL	1-RD..MULLER..F-309 GT

**CP&L**

Carolina Power &amp; Light Company

Company Correspondence

H. B. ROBINSON STEAM ELECTRIC PLANT  
Post Office Box 790  
Hartsville, South Carolina

February 7, 1974

Robinson File No. 2-0-4-a



Mr. Norman C. Moseley, Director  
U. S. Atomic Energy Commission  
Directorate of Regulatory Operations  
Region II - Suite 818  
230 Peachtree Street, N. W.  
Atlanta, Georgia 30303

50-261


Mr. John F. O'Leary  
Directorate of Licensing (Office of Regulation)  
U. S. Atomic Energy Commission  
Washington, D. C. 20545

Dear Sirs:

In accordance with Section 6.6.2 of the Technical Specifications the following abnormal occurrence is reported.

At 0933 hours on February 6, 1974, while preparing for a routine containment vessel inspection, it was discovered that the outer door to the personnel air lock was not locked as required. Subsequent investigation revealed that no entry was made to the containment after 1533 hours on February 5, 1974, therefore, the area had not been locked since that time.

This was reported to Mr. Herb Whitener of AEC-DRO on February 6, 1974.



JEM:ta

*Benny J. Furr*  
Benny J. Furr, Manager  
H. B. Robinson SEG Plant

1046