

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 10970

FILE: _____

FROM: CP&L Company Hartsville, S. C. Jack B. McGirt			DATE OF DOC 10-16-74	DATE REC'D 10-24-74	LTR	TWX	RPT	OTHER facsimile
TO: Mr. Norman C. Moseley			ORIG 1	CC	OTHER	SENT AEC PDR <u>xxxxxxx</u> SENT LOCAL PDR <u>xxxxxxx</u>		
CLASS	UNCLASS xxxxxxx	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-261		

DESCRIPTION:

Ltr Reporting Abnormal Occurrence on 10-15-74
concerning valve V2-160, motor- driven
AFW PUMP discharge valve to " O " STEAM
Generator failed to operate properly.....

ENCLOSURES:

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: H. B. Robinson #2

FOR ACTION/INFORMATION 10-24-74 JGB

BUTLER (L)	SCHWENCER (L)	ZIEMANN (L)	REGAN (E)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
CLARK (L)	STOLZ (L)	DICKER (E)	LEAR (L)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
PARR (L)	VASSALLO (L)	KNIGHTON (E)	
W/ Copies	W/ Copies	W/ Copies	W/ Copies
KNIEL (L)	PURPLE (L)	YOUNGBLOOD (E)	
W/ Copies	W/ Copies	W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u>	<u>TECH REVIEW</u>	<u>DENTON</u>	<u>LIC ASST</u>	<u>A/T IND</u>
<u>AEC PDR</u>		GRIMES		BRAITMAN
<u>OGC, ROOM P-506A</u>	<u>SCHROEDER</u>	GAMMILL	DIGGS (L)	SALTZMAN
<u>MUNTZING/STAFF</u>	<u>MACCARY</u>	KASTNER	GEARIN (L)	B. HURT
<u>CASE</u>	<u>KNIGHT</u>	BALLARD	GOULBOURNE (L)	
GIAMBUSSO	<u>PAWLICKI</u>	SPANGLER	KREUTZER (E)	<u>PLANS</u>
BOYD	<u>SHAO</u>		LEE (L)	MCDONALD
MOORE (L) (BWR)	<u>STELLO</u>	<u>ENVIRO</u>	MAIGRET (L)	CHAPMAN
DEYOUNG (L) (PWR)	<u>HOUSTON</u>	MULLER	REED (E)	DUBE w/input
SKOVHOLT (L)	<u>NOVAK</u>	DICKER	SERVICE (L)	E. COUPE
GOLLER (L)	<u>ROSS</u>	KNIGHTON	SHEPPARD (L)	
P. COLLINS	<u>IPPOLITO</u>	YOUNGBLOOD	SLATER (E)	<u>J. THOMPSON (2)</u>
DENISE	<u>TEDESCO</u>	REGAN	SMITH (L)	<u>KLECKER</u>
<u>REG OPR</u>	<u>LONG</u>	PROJECT LDR	<u>TEETS (L)</u>	<u>EISENHUT</u>
<u>FILE & REGION (3)</u>	<u>AINAS</u>		WILLIAMS (E)	
<u>MORRIS</u>	<u>BENAROYA</u>	<u>HARLESS</u>	WILSON (L)	
<u>STEELE</u>	<u>VOLIMER</u>			

EXTERNAL DISTRIBUTION

<u>1 - LOCAL PDR Hartsville, SC</u>	<u>1 - NATIONAL LABS</u>	<u>1 - PDR-SAN/LA/NY</u>
<u>1 - TIC (ABERNATHY) (1)(2)(10)</u>	<u>1 - ASLBP (E/W Bldg, Rm 529)</u>	<u>1 - BROOKHAVEN NAT LAB</u>
<u>1 - NSIC (BUCHANAN)</u>	<u>1 - W. PENNINGTON, Rm E-201 GT</u>	<u>1 - G. ULRIKSON, ORNL</u>
<u>1 - ASLB</u>	<u>1 - B&M SWINEBROAD, Rm E-201 GT</u>	<u>1 - AGMED (RUTH GUSSMAN)</u>
<u>1 - Newton Anderson</u>	<u>1 - CONSULTANTS</u>	<u>Rm B-127 GT</u>
<u>1 - ACRS HOLDING</u>	<u>NEWMARK/BLUME/AGBABIAN</u>	<u>1 - R. D. MUELLER, Rm E-201 GT</u>

5 SENT to Lic Asst.
TEETS

Frank Logan

Carolina Power & Light Company

Robinson Steam Generating Plant

Post Office Box 723

Winston-Salem, North Carolina 27102

October 15, 1974

Robinson File No. 2-0-4-a-1

Regulatory

File Cy.

Mr. Norman C. Moseley, Director
U. S. Atomic Energy Commission
Directorate of Regulatory Operations
Region II - Suite 818
230 Peachtree Street, N.W.
Atlanta, Georgia 30303

Mr. Edison Case, Acting Director
Directorate of Licensing (Office of Regulation)
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Sirs:

In accordance with Section 6.6.2.2 of the Robinson Plant Technical Specifications, the following Abnormal Occurrence is reported:

At 1747 on October 15, 1974, while performing PT-22, Auxiliary Feeder System Periodic Test (monthly), valve V2-160, motor-driven AFW pump discharge valve to "C" Steam Generator, failed to operate properly. The Steam-driven AFW pump was test operated immediately and its discharge valve to "C" Steam Generator successfully tested, demonstrating the ability to feed "C" Steam Generator in an emergency. V2-160 was repaired and returned to service at 0121 on October 16, 1974.

This was reported to Mr. Austin Hardin of DRO on October 15, 1974.

