

**AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL**  
(TEMPORARY FORM)

CONTROL NO: 3095

FILE: A610

FROM: Carolina Power & Light Company Hartsville, S. C. Benny J. Furr			DATE OF DOC 4-8-74	DATE REC'D 4-8-74	LTR	MEMO	RPT	OTHER Facsimile
TO: John F. O'Leary			ORIG	CC	OTHER	SENT AEC PDR X SENT LOCAL PDR X		
CLASS XXXX	UNCLASS	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-261		

**DESCRIPTION:**  
Facsimile, reporting an Abnormal Occurrence on 4-6-74 in which "A" Boric Acid Transfer Pump failed while recirculating the contents of "A" Boric Acid Storage Tank.....

**ENCLOSURES:**

**ACKNOWLEDGED**

**Do Not Remove**

PLANT NAME: H. B. Robinson Unit # 2

FOR ACTION/INFORMATION

4-9-74

AB

BUTLER(L) W/ Copies	SCHWENCER(L) W/ Copies	ZIEMANN(L) W/ Copies	REGAN(E) W/ Copies
CLARK(L) W/ Copies	STOLZ(L) W/ Copies	DICKER(E) W/ Copies	W/ Copies
GOLLER(L) W/ Copies	VASSALLO(L) W/ Copies	KNIGHTON(E) W/ Copies	W/ Copies
KNIEL(L) W/ Copies	✓SCHEMEL(L) W/7 Copies	YOUNGBLOOD(E) W/ Copies	W/ Copies

**INTERNAL DISTRIBUTION**

✓ <u>REG FILE</u>	<u>TECH REVIEW</u>	DENTON	<u>A/T IND</u>
✓ <u>AEC PDR</u>	✓HENDRIE	GRIMES	BRAITMAN
✓OGC, ROOM P-506A	SCHROEDER	GAMMILL	SALTZMAN
✓MUNTZING/STAFF	✓MACCARY	KASTNER	B. HURT
✓CASE	✓KNIGHT	BALLARD	<u>PLANS</u>
GIAMBUSO	✓PAWLICKI	SPANGLER	MCDONALD
BOYD	✓SHAO		DUBE w/Input
MOORE (L)(BWR)	✓STELLO	<u>ENVIRO</u>	<u>INFO</u>
DEYOUNG(L)(PWR)	✓HOUSTON	MULLER	C. MILES
✓SKOVHOLT (L)	✓NOVAK	DICKER	✓B. KING
P. COLLINS	✓ROSS	KNIGHTON	✓KLECKER
DENISE	✓IPPOLITO	YOUNGBLOOD	✓EISENHUT
<u>REG OPR</u>	✓TEDESCO	REGAN	
✓FILE & REGION(3)	✓LONG	PROJECT LDR	
✓MORRIS	✓LAINAS		
✓STEELE	✓BENAROYA	HARLESS	
	✓VOLLMER		

**EXTERNAL DISTRIBUTION**


✓1 - LOCAL PDR Hartville, S. C.	(1)(2)(10)-NATIONAL LAB'S	1-PDR-SAN/LA/NY
✓1 - DTIE(ABERNATHY)	1-ASLBP(E/W Bldg, Rm 529)	1-GERALD LELLOUCHE
✓1 - NSIC(BUCHANAN)	1-W. PENNINGTON, Rm E-201 GT	BROOKHAVEN NAT. LAB
1 - ASLB(YORE)	1-CONSULTANT'S	1-AGMED(Ruth Gussman)
	NEWMARK/BLUME/AGBABIAN	RM-B-127, GT.
✓16 - CYS ACRS HOLDING SENT TO LIC ASST.	1-GERALD ULRIKSON...ORNL	1-RD..MULLER..F-309 GT
S. TEETS ON 4-9-74		

**CP&L**

Carolina Power &amp; Light Company

H. B. ROBINSON STEAM ELECTRIC PLANT  
Post Office Box 790  
Hartsville, South Carolina

April 8, 1974



Robinson File No. 2-0-4-a-1

50-261

Mr. Norman C. Moseley, Director  
U. S. Atomic Energy Commission  
Directorate of Regulatory Operations  
Region II - Suite 818  
230 Peachtree Street, N.W.  
Atlanta, Georgia 30303

Mr. John F. O'Leary  
Directorate of Licensing (Office of Regulation)  
U. S. Atomic Energy Commission  
Washington, D. C. 20545

Dear Sirs:

In accordance with Section 6.6.2 of the Technical Specifications, the following abnormal occurrence is reported.

At 0907 hours on April 6, 1974, "A" Boric Acid Transfer Pump failed while recirculating the contents of "A" Boric Acid Storage Tank. "B" Boric Acid Transfer Pump was operable at this time, therefore, the system continued to perform its intended function.


This was reported to Mr. Herb Whitener of AEC DRO by telephone on April 6, 1974.

Yours very truly,

*Benny J. Furr (JFM)*

Benny J. Furr, Manager  
H. B. Robinson SEG Plant

JFM: rbs



3095