

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 3225

FILE: A10

FROM: Carolina Power & Light Hartsville, S. C. Benny J. Furr			DATE OF DOC 4-11-74	DATE REC'D 4-12-74	LTR	MEMO	RPT	OTHER TWX
TO: Norman C. Moseley			ORIG	CC 1	OTHER	SENT AEC PDR XXX SENT LOCAL PDR XXX		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-261		

DESCRIPTION:

Twx furn info re abnormal occurrence of 4-11-74
in which Primary Heat Trace Circuit #2 failed

ENCLOSURES:

DO NOT REMOVE
ACKNOWLEDGED

PLANT NAME: H. B. ROBINSON UNIT #2

FOR ACTION/INFORMATION 4-12-74 GMC

BUTLER(L) W/ Copies	SCHWENCER(L) W/ Copies	ZIEMANN(L) W/ Copies	REGAN(E) W/ Copies
CLARK(L) W/ Copies	STOLZ(L) W/ Copies	DICKER(E) W/ Copies	W/ Copies
GOLLER(L) W/ Copies	VASSALLO(L) W/ Copies	KNIGHTON(E) W/ Copies	W/ Copies
KNIEL(L) W/ Copies	✓ SCHEMEL(L) W/7 Copies	YOUNGBLOOD(E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

✓ <u>REG FILE</u> ✓ AEC PDR ✓ OGC, ROOM P-506A ✓ MUNTZING/STAFF ✓ CASE GIAMBUSO BOYD MOORE (L) (BWR) ✓ DEYOUNG (L) (PWR) ✓ SKOVHOLT (L) P. COLLINS DENISE ✓ <u>REG OPR</u> ✓ FILE & REGION(3) ✓ MORRIS ✓ STEELE	✓ <u>TECH REVIEW</u> ✓ HENDRIE ✓ SCHROEDER ✓ MACCARY ✓ KNIGHT ✓ PAWLICKI ✓ SHAO ✓ STELLO ✓ HOUSTON ✓ NOVAK ✓ ROSS ✓ IPPOLITO ✓ TEDESCO ✓ LONG ✓ LAINAS ✓ BENAROYA ✓ VOLLMER	DENTON GRIMES GAMMILL KASTNER BALLARD SPANGLER ✓ <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	<u>LIC ASST</u> DIGGS (L) GEARIN (L) GOULBOURNE (L) LEE (L) MAIGRET (L) REED (E) SERVICE (L) SHEPPARD (L) SLATER (E) SMITH (L) ✓ TEETS (L) WADE (E) WILLIAMS (E) WILSON (L)	<u>A/T IND</u> BRAITMAN SALTZMAN B. HURT <u>PLANS</u> MCDONALD DUBE w/Input <u>INFO</u> ✓ C. MILES ✓ B. KING ✓ KLECKER ✓ EISENHUT
--	---	---	---	--

EXTERNAL DISTRIBUTION

✓ 1 - LOCAL PDR HARTVILLE, SC ✓ 1 - DTIE (ABERNATHY) ✓ 1 - NSIC (BUCHANAN) 1 - ASLB (YORE) ✓ 16 - CYS ACRS HOLDING Sent to Lic Asst Teets 4-12-74	(1) (2) (10) NATIONAL LAB'S 1-ASLBP (E/W Bldg, Rm 529) 1-W. PENNINGTON, Rm E-201 GT 1-CONSULTANT'S NEWMARK/BLUME/AGBABIAN 1-GERALD ULRIKSON...ORNL	1-PDR-SAN/LA/NY 1-GERALD LELLOUCHE BROOKHAVEN NAT. LAB 1-AGMED (Ruth Gussman) RM-B-127, GT. 1-RD..MULLER..F-309 GT
---	---	---



Regulatory


File Cy.

Carolina Power & Light Company

H. B. ROBINSON STREAM ELECTRIC PLANT
Post Office Box 790
Hartsville, South Carolina

April 11, 1974

Robinson File No. 2-0-4-a-1



Mr. Norman C. Moseley, Director
U. S. Atomic Energy Commission
Directorate of Regulatory Operations
Region II - Suite 818
230 Peachtree Street, N.W.
Atlanta, Georgia 30303

50-261

Mr. John F. O'Leary
Directorate of Licensing (Office of Regulation)
U. S. Atomic Energy Commission
Washington, D. C. 20545


Dear Sirs:


In accordance with Section 6.6.2 of the Technical Specifications the following abnormal occurrence is reported.

At 0610 on April 11, 1974, Primary Heat Trace Circuit No. 2 failed. Investigation revealed that one leg of this circuit was open and grounded rendering it inoperable. New cable was installed and the circuit declared operable at 1400 hours. The secondary circuit remained operable, therefore, no safety hazard existed.

This was reported to Mr. Herb Whitener of AEC DRO by telephone on April 11, 1974.

Yours very truly,


Benny J. Furr, Manager
H. B. Robinson SEG Plant



JEM:gg

3225