

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 3665

FROM: Carolina Power & Light Co. Hartville, South Carolina Benny J. Furr		DATE OF DOC: 6-6-73	DATE REC'D 6-6-73	LTR	MEMO	RPT	OTHER TWX
TO: John F. O'Leary		ORIG 1	CC	OTHER	SENT AEC PDR X SENT LOCAL PDR X		
CLASS: <u>U</u> PROP INFO		INPUT	NO CYS REC'D 1		DOCKET NO: 50-261		

DESCRIPTION:

TWX reporting Abnormal Occurrence on narrow range containment pressure indicator.....
3 3/8 inch vent valves on pressure sensing line to all containment pressure transmitters were open.....

ENCLOSURES:

DO NOT REMOVE

PLANT NAMES: H. B. Robinson, Unit # 2

FOR ACTION/INFORMATION

6-6-73 fod

BUTLER(L) W/ Copies	SCHWENCER(L) W/ Copies	ZIEMANN(L) W/ Copies	YOUNGBLOOD(E) W/ Copies
CLARK(L) W/ Copies	STOLZ(L) W/ Copies	ROUSE(FM) W/ Copies	REGAN(E) W/ Copies
GOLLER(L) W/ Copies	VASSALLO(L) W/ Copies	DICKER(E) W/ Copies	W/ Copies
KNIEL(L) W/ Copies	SCHMEL (L) W/7 Copies	KNIGHTON(E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION


<u>REG FILE</u>	<u>TECH REVIEW</u>	DENTON	F & M	WADE	E
<u>AEC PDR</u>	<u>HENDRIE</u>	GRIMES	SMILEY	BROWN	E
<u>OGC, ROOM P-506A</u>	<u>SCHROEDER</u>	GAMMILL	NUSSBAUMER	G. WILLIAMS	E
<u>MUNTZING/STAFF</u>	<u>MACCARY</u>	KASTNER		SHEPPARD	E
<u>CASE</u>	<u>KNIGHT</u>	BALLARD	<u>LIC ASST.</u>		
GIAMBUSSO	<u>PAWLICKI</u>	SPANGLER	<u>SERVICE</u>	L	<u>A/T IND</u>
BOYD	<u>SHAO</u>		WILSON	L	<u>BRAITMAN</u>
V. MOORE-L(BWR)	<u>STELLO</u>	ENVIRO	GOULBOURNE	L	<u>SALTZMAN</u>
DEYOUNG-L(PWR)	<u>HOUSTON</u>	<u>MULLER</u>	SMITH	L	
<u>SKOVHOLT-L</u>	<u>NOVAK</u>	DICKER	GEARIN	L	<u>PLANS</u>
P. COLLINS	<u>ROSS</u>	KNIGHTON	DIGGS	L	<u>MCDONALD</u>
	<u>IPPOLITO</u>	YOUNGBLOOD	<u>TEETS</u>	L	<u>DUBE</u>
REG OPR	<u>TEDESCO</u>	REGAN	LEE	L	
<u>FILE & REGION(3)</u>	<u>LONG</u>	PROJ LEADER	MAIGRET	L	<u>INFO</u>
<u>MORRIS</u>	<u>LAINAS</u>		SHAFFER	F & M	<u>C. MILES</u>
<u>STEELE</u>	<u>BENAROYA</u>	<u>HARLESS</u>			
	<u>VOLLMER</u>				

EXTERNAL DISTRIBUTION

<u>1-LOCAL PDR</u> Hartville, S. C.	(1)(2)(9)-NATIONAL LAB'S	1-PDR-SAN/LA/NY
<u>1-DTIE</u> (ABERNATHY)	1-R. CARROLL-C, GT-B227	1- GERALD LELLOUCHE
<u>1-NSIC</u> (BUCHANAN)	1- R. CATLIN,E-256-GT	BROOKHAVEN NAT. LAB
1-ASLB-YORE/SAYRE	1- CONSULTANT'S	1-AGMED(WALTER KOESTER,
WOODWARD/H ST.	NEWMARK/BLUME/AGABIAN	RM C-427, GT)
<u>16-CYS ACRS</u> XXXXXXXX Sent 6-6-73 to	1- GERLAD ULRIKSON....ORNL	1- RD...MULLER...F-309GT
S. Teets for Dist.		

Regulatory

File Cy:



50-261

NNNN"!!#

R B

TWX 942

USAEC HQS GTWN

WU WSH TLXA145 WAA130(1252)(2-102627E157)PD 06/06/73 1252

ICS IPMMTZZ CSP

8033321351 TDMT HARTSVILLE SC 143 06-06 1252P EST

PMS MR JOHN F OLEARY DIRECTOR DIRECTORATE OF LICENSING U.S.
ATOMIC ENERGY COMMISSION , DLR

WASHINGTON DC 20545

IN ACCORDANCE WITH SECTION 6.6.2 OF THE TECHNICAL SPECIFICATION,
THE FOLLOWING ABNORMAL OCCURANCE IS REPORTED:

AT 1430 HOURS ON 6-5-73, WHILE INVESTIGATING AND ABNORMAL INDICATION
ON THE NARROW RANGE CONTAINMENT PRESSURE INDICATUR, IT WAS
FOUND THAT 3 3/8 INCH VENT VALVES ON THE PRESSURE SENSING LINE
TO ALL CONTAINMENT PRESSURE TRANSMITTERS WERE OPEN. THIS RESULTED
IN ERRONEOUS SIGNALS TO PTS 950, 951, 952, 953, 954, AND 955,
WHICH SUPPLY INPUTS TO RTGB INDICATORS AND SAFEGUARD RACKS.

THE VENT VALVES WERE CLOSED AND PLUGS INSTALLED TO PREVENT RECURRENCE

OF THIS INCIDENT. AS A FURTHER PRECAUTION, THESE VALVES HAVE
BEEN ADDED TO THE CHECK OFF SHEET WHICH ESTABLISHES CONTAINMENT
INTEGRITY.


THIS INCIDENT HAS BEEN REVIEWED BY THE PLANT NUCLEAR SAFETY
COMMITTEE AND SAFE REACTOR OPERATION IS ASSURED.

THIS WAS REPORTED TO MR BILL SIEDLE OF DRO BY TELEPHONE ON 6-6-73.

MR BENNY J FURR, MANAGER /H B ROBINSON SEG PLANT

245P JUN 6

USAEC HQS GTWN



[3665