

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 4038

FILE: _____

FROM: Carolina Power & Light Company Hartsville S. C. B. J. Furr			DATE OF DOC 6-21-73	DATE REC'D 6-22-73	LTR x	MEMO	RPT	OTHER
TO: John F. O'Leary			ORIG 1	CC	OTHER	SENT AEC PDR x SENT LOCAL PDR x		
CLASS	UNCLASS x	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-261		

DESCRIPTION:
Ltr reporting an abnormal occurrence on 6-20-73, in whic a turbine trip occurred while performing a test of the turbine redundant overspeed trip system....

PLANT NAME: H. B. Robinson

ENCLOSURES:

DO NOT REMOVE

FOR ACTION/INFORMATION 6-22-73 LB

BUTLER(L)	SCHWENCER(L)	ZIEMANN(L)	REGAN(E)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
CLARK(L)	STOLZ(L)	DICKER(E)	
W/ Copies	W/ Copies	W/ Copies	W/ Copies
GOLLER(L)	VASSALLO(L)	KNIGHTON(E)	
W/ Copies	W/ Copies	W/ Copies	W/ Copies
KNIEL(L)	✓SCHEMEL(L)	YOUNGBLOOD(E)	
W/ Copies	W/ 7 Copies	W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u>	<u>TECH REVIEW</u>	<u>DENTON</u>	<u>LIC ASST</u>	<u>A/T IND</u>
✓AEC PDR	✓HENDRIE	GRIMES	BROWN (E)	BRAITMAN
✓OGC, ROOM P-506A	SCHROEDER	GAMMILL	DIGGS (L)	SALTZMAN
✓MUNTZING/STAFF	✓MACCARY	KASTNER	GEARIN (L)	
✓CASE	✓KNIGHT	BALLARD	GOULBOURNE (E)	<u>PLANS</u>
GIAMBUSSO	✓PAWLICKI	SPANGLER	LEE (L)	MCDONALD
BOYD	✓SHAO		MAIGRET (L)	DUBE
MOORE (L)(BWR)	✓STELLO	<u>ENVIRO</u>	SERVICE (L)	
DEYOUNG(L)(PWR)	✓HOUSTON	MULLER	SHEPPARD (E)	<u>INFO</u>
✓SKOVHOLT (L)	✓NOVAK	DICKER	SMITH (L)	C. MILES
P. COLLINS	✓ROSS	KNIGHTON	✓TEETS (L)	✓B. KING (Reg Opr
	✓IPPOLITO	YOUNGBLOOD	WADE (E)	E/W Bldg) (OOE)
<u>REG OPR</u>	✓TEDESCO	REGAN	WILLIAMS (E)	
✓FILE & REGION(3)	✓LONG	PROJECT LDR	WILSON (L)	
✓MORRIS	✓LAINAS			
✓STEELE	✓BENAROYA	<u>HARLESS</u>		
	✓VOLLMER			


EXTERNAL DISTRIBUTION

✓1 - LOCAL PDR Hartsville, S. C.	(1)(2)(9)-NATIONAL LAB'S	1-PDR-SAN/LA/NY
✓1 - DTIE(ABERNATHY)	1-R. CARROLL-OC,GT-B227	1-GERALD LELLOUCHE
✓1 - NSIC(BUCHANAN)	1-R. CATLIN, E-256-GT	BROOKHAVEN NAT. LAB
1 - ASLB(YORE/SAYRE/ WOODARD/"H" ST.	1-CONSULTANT'S	1-AGMED(WALTER KOESTER
✓16 - CYS ACRS XXXXXX SENT TO LIC ASST	NEWMARK/BLUME/AGBABIAN	RM-C-427-GT
S. TEETS 6-22-73	1-GERALD ULRIKSON...ORNL	1-RD..MULLER..F-309 GT

Regulatory


File Cy.

WESTERN UNION INCOMING



1973 JUN 21 PM 4 30

50-261

U.S. ATOMIC ENERGY COMM.
TWX UNIT

WU WSH

+
USAEC HQS GTWNTLXA081 WAG144(1426)(2-234151E172)PD 06/21/73 1426
ICS IPMMTZZ CSP8033321351 TDMT HARTSVILLE SC 118 06-21 0226P EST
PMS JOHN S OLEARY
DIRECTORATE OF LICENSING US ATOMIC ENERGY COMMISSION
WASHINGTON DC 20545

IN ACCORDANCE WITH 6.6.2 OF THE TECHNICAL SPECIFICATION, THE FOLLOWING ABNORMAL OCCURENCE IS REPORTED: ON JUNE 20, 1973, AT 1454 HOURS WHILE PERFORMING A TEST OF THE TURBINE REDUNDANT OVERSPEED TRIP SYSTEM (TROTS) A TURBINE TRIP OCCURRED. AN IMMEDIATE REACTOR TRIP DID NOT OCCUR DUE TO A TURBINE STOP VALVE LIMIT SWITCH MALFUNCTION. A REACTOR TRIP DID OCCUR DUE TO HIGH PRESSURIZER PRESSURE.

THE TURBINE STOP VALVE LIMIT SWITCH WAS ADJUSTED AND SATISFACTORILY OPERATED PRIOR TO INITATING POWER OPERATION.

THE INCIDENT HAS BEEN REVIEWED BY THE PLANT NUCLEAR SAFETY COMMITTEE

AND SAFE REACTOR OPERATION IS ASSURED.

THIS WAS REPORTED TO MR SIEDLE OF DRO BY TELEPHONE ON JUNE 21 1973

B J FURR PLANT MGR CAROLINA POWER AND LIGHT CO H B ROBINSON
SEG PLANT HARTSVILLE SC PO BOX 790 29550

+
USAEC HQS GTWN

431P EDT

WU WSH

4038