

FILE: A/b

FROM: Carolina Power & Light Co. Hartsville, South Carolina Benny J. Furr			DATE OF DOC 5-13-74	DATE REC'D 5-13-74	LTR	MEMO	RPT	OTHER TWX
TO: Norman C. Moseley			ORIG 1	CC	OTHER	SENT AEC PDR XXX SENT LOCAL PDR XXX		
CLASS	UNCLASS	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-261		
			XXX					
DESCRIPTION: Twx furn info re abnormal occurrence #2-0-4-a-1 of 5-11-74 in which a leak from a secondary system valve was found to be contaminated water				ENCLOSURES: DO NOT REMOVE ACKNOWLEDGED				
PLANT NAME: H. B. ROBINSON UNIT #2								

FOR ACTION/INFORMATION

5-14-74 GMC

BUTLER(L)	SCHWENCER(L)	ZIEMANN(L)	REGAN(E)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
CLARK(L)	STOLZ(L)	DICKER(E)	
W/ Copies	W/ Copies	W/ Copies	W/ Copies
PARR(L)	VASSALLO(L)	KNIGHTON(E)	
W/ Copies	W/ Copies	W/ Copies	W/ Copies
KNIEL(L)	PURPLE (L)	YOUNGBLOOD(E)	
W/ Copies	W/7 Copies	W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u>	<u>TECH REVIEW</u>	DENTON	LIC ASST	<u>A/T IND</u>
✓AEC PDR	✓HENDRIE	GRIMES		BRAITMAN
✓OGC, ROOM P-506A	✓SCHROEDER	GAMMILL	DIGGS (L)	SALTZMAN
✓MUNTZING/STAFF	✓MACCARY	KASTNER	GEARIN (L)	B. HURT
✓CASE	✓KNIGHT	BALLARD	GOULBOURNE (L)	<u>PLANS</u>
GIAMBUSSO	✓PAWLICKI	SPANGLER	LEE (L)	MCDONALD
BOYD	✓SHAO		MAIGRET (L)	DUBE w/Input
MOORE (L)(BWR)	✓STELLO	<u>ENVIRO</u>	REED (E)	<u>INFO</u>
DEYOUNG(L)(PWR)	✓HOUSTON	MULLER	SERVICE (L)	C. MILES
SKOVHOLT (L)	✓NOVAK	DICKER	SHEPPARD (L)	✓KLECKER
✓GOLLER(L)	✓ROSS	KNIGHTON	SLATER (E)	✓EISENHUT
P. COLLINS	✓IPPOLITO	YOUNGBLOOD	SMITH (L)	
DENISE	✓TEDESCO	REGAN	✓TEETS (L)	
✓REG OPR	✓LONG	PROJECT LDR	WADE (E)	✓AOR FILE
FILE & REGION(3)	✓LAINAS		WILLIAMS (E)	D. THOMPSON (2)
✓MORRIS	✓BENAROYA	HARLESS	WILSON (L)	
	✓VOLLMER			

EXTERNAL DISTRIBUTION

✓1 - LOCAL PDR HARTVILLE, SC	(1)(2)(10)-NATIONAL LAB'S	1-PDR-SAN/LA/NY
✓1 - TIC (ABERNATHY)	1-ASLBP(E/W Bldg, Rm 529)	1-GERALD LELLOUCHE
✓1 - NSIC(BUCHANAN)	1-W. PENNINGTON, Rm E-201 GT	BROOKHAVEN NAT. LAB
1 - ASLB	1-CONSULTANT'S	1-AGMED(Ruth Gussman)
1 - F. R. DAVIS (AEROJET NUCLEAR)	NEWMARK/BLUME/AGBABIAN	RM-B-127, GT.
✓16 - CYS ACRS HOLDING	1-GERALD ULRIKSON...ORNL	1-ED..MULLER..F-309 GT
Sent to Lic Asst Teets 5-14-74	1-B & M SWINEBROAD, Rm E-201 GT	

CP&L

Carolina Power & Light Company

H. B. ROBINSON STEAM ELECTRIC PLANT
Post Office Box 790
Hartsville, South Carolina

May 13, 1974

Robinson File No. 2-0-4-a-1

50-261

Mr. Norman C. Moseley, Director
U. S. Atomic Energy Commission
Directorate of Regulatory Operations
Region II - Suite 818
230 Peachtree Street, N. W.
Atlanta, Georgia 30303

50-261

Mr. John F. O'Leary
Directorate of Licensing (Office of Regulation)
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Sirs:

In accordance with Section 6.6.2 of the Technical Specification the following abnormal occurrence is reported.



On May 11, 1974, a leak from a secondary system valve was found to be contaminated water. On the previous day the leakage was not contaminated. Investigation showed that a leaking isolation valve allowed water from the steam generator to reach the second valve which had been dismantled for maintenance. The incident resulted in 147 millicuries of gross activity being released to the storm drain system in approximately 360 gallons of water.

No significant exposure to the general public resulted from this incident.

All maintenance personnel have been advised to use caution when breaking secondary system boundaries due to potential of contamination in the secondary plant and comprehensive contamination surveys are being performed daily in the turbine building.

The event is reported as violation of section 3.0.1 of the Technical Specification.

~~3.9.1~~
3.9.1



REGULATORY DOCKET FILE COPY

4295

- 2 -

Letter to Moselny and O'Leary Cont'd.

May 13, 1974

This incident was reported to Marvin Sinkule, AEC-DRO, on May 11, 1974.
A 10-day report will follow.

Yours very truly,



Benny J. Furr, Manager
H. B. Robinson SFG Plant

RJP:ta