

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 6030

FILE:

FROM: Carolina Power & Light Co. Hartsville, S.C. Mr. B.J. Furr			DATE OF DOC 8-7-73	DATE REC'D 8-7-73	LTR	MEMO	RPT	OTHER TWX
TO: J.S. O'Leary			ORIG 1	CC	OTHER	SENT AEC PDR <u>XXX</u> SENT LOCAL PDR <u>XXX</u>		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-261		

DESCRIPTION:
Twx in accordance with 6.6.2A of Tech.
Specs. reporting error in the initial
volume calculation of the Safety Injections.
Accumulators.

ENCLOSURES:

DO NOT REMOVE

PLANT NAME: H.B. Robinson

FOR ACTION/INFORMATION 8-7-73 jdb

BUTLER(L)	SCHWENCER(L)	ZIEMANN(L)	REGAN(E)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
CLARK(L)	STOLZ(L)	DICKER(E)	
W/ Copies	W/ Copies	W/ Copies	W/ Copies
GOLLER(L)	VASSALLO(L)	KNIGHTON(E)	
W/ Copies	W/ Copies	W/ Copies	W/ Copies
KNIEL(L)	SCHEMEL(L)	YOUNGBLOOD(E)	
W/ Copies	W/7 Copies	W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u>	<u>TECH REVIEW</u>	DENTON	<u>LIC ASST</u>	<u>A/T IND</u>
✓ AEC PDR	✓ HENDRIE	GRIMES	BROWN (E)	BRAITMAN
✓ OGC, ROOM P-506A	✓ SCHROEDER	GAMMILL	DIGGS (L)	SALTZMAN
✓ MUNTZING/STAFF	✓ MACCARY	KASTNER	GEARIN (L)	
✓ CASE	✓ KNIGHT	BALLARD	GOULBOURNE (L)	<u>PLANS</u>
GIAMBUSO	✓ PAWLICKI	SPANGLER	LEE (L)	MCDONALD
BOYD	✓ SHAO		MAIGRET (L)	DUBE
MOORE (L) (BWR)	✓ STELLO	<u>ENVIRO</u>	SERVICE (L)	
✓ DEYOUNG (L) (PWR)	✓ HOUSTON	MULLER	SHEPPARD (E)	<u>INFO</u>
✓ SKOVHOLT (L)	✓ NOVAK	DICKER	SMITH (L)	C. MILES
P. COLLINS	✓ ROSS	KNIGHTON	✓ TEETS (L)	✓ B. King (Reg.Op) (OOE)
	✓ IPPOLITO	YOUNGBLOOD	WADE (E)	E/W Towers
✓ REG OPR	✓ TEDESCO	REGAN	WILLIAMS (E)	
FILE & REGION(3)	✓ LONG	PROJECT LDR	WILSON (L)	
✓ MORRIS	✓ LAINAS			
✓ STEELE	✓ BENAROYA	HARLESS		
	✓ VOLIMER			

EXTERNAL DISTRIBUTION

✓ 1 - LOCAL PDR <u>Hartsville, S.C.</u>	(1)(2)(9)-NATIONAL LAB'S	1-PDR-SAN/LA/NY
✓ 1 - DTIE(ABERNATHY)	1-R.Schoonmaker, OC, GT, D-323	1-GERALD LELLOUCHE
✓ 1 - NSIC(BUCHANAN)	1-R. CATLIN, E-256-GT	BROOKHAVEN NAT. LAB
1 - ASLB(YORE/SAYRE/ WOODARD/"H" ST.	1-CONSULTANT'S	1-AGMED(WALTER KOESTER
✓ 16 - CYS ACRS HOLDING Sent To S. Teets	NEWMARK/BLUME/AGBABIAN	RM-C-427-GT
8-7-73	1-GERALD ULRIKSON...ORNL	1-RD..MULLER..F-309 GT

USAEC HQS GTWN

50-261

WU RB BCH WSH

TLX RBC042 (RELAY) 1345 2-233510E217 2033321351)

TEMT TARTSVILLE SC 91 07-06 0145P EST

MR JOHN S OLEAVY DIRECTOR OF LICENSING

GEOXXX GERMANTOWN MD (WASHDC)

IN ACORDECE WITH SECTION 5.5.2.A OF THE TECHNICAL SPECIFICATIONS
THE FOLLOWING ADMORAL ACCORDANCE IS REPORT.

DUE TO AN ERROR IN THE INITIAL VOLUME CALCULATION OF THE SAFETY
INJECTIONS ACCUMULATORS SLIGHTLY LEFT THAN REQUIRED. VOLUMES HAVE
NEED EXPIERENCED BY THE REACTOR WAS OPERATING AT TOWER.

THE MINIMUM LEVELS DURING TT PERIODS WERE APPORIXMATELY 99.3
PER CENT OF THAT WHICH IS REQUIRED BY THE TECHNICAL SPECIFICATION.
NEW ALARMS SET POINTS HAD BEEN ESTALIBHS TO PREVENT RECURRENCE
OF THIS PROBLEM.


THIS WAS REPORTED TO MR BILL SIEDLE OF D.R.O. BY TELEPHONE
ON AUG. 6TH, 1973.

BENNY J FURR, MANAGER H. B. ROBINSON SEG PLANTS.

USAEC HQS GTWN
AUG 6 1235P EDT

WU RB BCH WSH

#



6030

WESTERN UNION INCOMING

USAEC HQS GTWN

1973 AUG 7 PM 12 41

WU RB BCH WSH

U.S. ATOMIC ENERGY COMM.
TWX UNIT

TLX RBC042 (RELAY) 1345 2-033510E218 8033321351)

TDMT TARTSVILLE SC 91 08-06 0145P EST

MR JOHN S O'LEAVY DIRECTOR OF LICENSING

GEOXXX GERMANTOWN MD (WASHDC)


IN ACORDENCE WITH SECTION 6.6.2.A OF THE TECHNICAL SPECIFICATIONS
THE FOLLOWING ADNORMAL ACCORDANCE IS REPORT.

DUE TO AN ERROR IN THE INITIAL VOLUME CALCULATION OF THE SAFETY
INJECTIONS ACCUMULATORS SLIGHTLY LEFT THAN REQUIRED VOLUMES HAVE
NEED EXPIERENCED BY THE REACTOR WAS OPERATING AT TOWER.

THE MINIMUM LEVELS DURING TT PERIODS WERE APPORIXMATELY 99.3
PER CENT OF THAT WHICH IS REQUIRED BY THE TECHNICAL SPECIFICATION.
NEW ALARAMS SET POINTS HAD BEEN ESTALIBHS TO PREVENT RECURRENCE
OF THIS PROBLEM.

THIS WAS REPORTED TO MR BILL SIEDLE OF D.R.O. BY TELEPHONE
ON AUG. 6TH, 1973.

BENNY J FURR, MANAGER H. B. ROBINSON SEG PLANTS.



USAEC HQS GTWN

AUG 6 1235P EDT

WESTERN UNION INCOMING

WU RB BCH WSH

~~6658~~