

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL  
(TEMPORARY FORM)

CONTROL NO: 6475

FILE: \_\_\_\_\_

FROM: Carolina Power & Light Company Hartville, South Carolina Benny J. Furr			DATE OF DOC 8-24-73	DATE REC'D 8-24-73	LTR	MEMO	RPT	OTHER TWX
TO: John F. O'Leary			ORIG 1	CC	OTHER	SENT AEC PDR * SENT LOCAL PDR *		
CLASS	UNCLASS XXXX	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-261		

DESCRIPTION:  
TWX reporting an abnormal occurrence on 8-24-73 re...setpoint for high steam flow was above limit in table 3.5-1 of Tech Specs.....

ENCLOSURES:

DO NOT REMOVE

PLANT NAME: H. B. Robinson, Unit # 2

FOR ACTION/INFORMATION 8-25-73 fod

BUTLER(L) W/ Copies	SCHWENCER(L) W/ Copies	ZIEMANN(L) W/ Copies	REGAN(E) W/ Copies
CLARK(L) W/ Copies	STOLZ(L) W/ Copies	DICKER(E) W/ Copies	W/ Copies
GOLLER(L) W/ Copies	VASSALLO(L) W/ Copies	KNIGHTON(E) W/ Copies	W/ Copies
KNIEL(L) W/ Copies	<del>SCHEMEL(L)</del> W/7 Copies	YOUNGBLOOD(E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u> <del>AEC PDR</del> <del>OGC, ROOM P-506A</del> <del>MUNTZING/STAFF</del> <del>CASE</del> GIAMBUSSO BOYD MOORE (L)(BWR) DEYOUNG(L)(PWR) <del>SKOVHOLT (L)</del> P. COLLINS  <u>REG OPR</u> <del>FILE &amp; REGION(3)</del> <del>MORRIS</del> <del>STEELE</del>	<u>TECH REVIEW</u> <del>HENDRIE</del> <del>SCHROEDER</del> <del>MACCARY</del> <del>KNIGHT</del> <del>PAWLICKI</del> <del>SHAO</del> <del>STELLO</del> <del>HOUSTON</del> <del>NOVAK</del> <del>ROSS</del> <del>IPPOLITO</del> <del>TEDESCO</del> <del>LONG</del> <del>LAINAS</del> <del>BENAROYA</del> <del>VOLLMER</del>	DENTON GRIMES GAMMILL KASTNER BALLARD SPANGLER  <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR  HARLESS	<u>LIC ASST</u> DIGGS (L) GEARIN (L) GOULBOURNE (L) LEE (L) MAIGRET (L) SERVICE (L) SHEPPARD (E) SMITH (L) <del>TEETS (L)</del> WADE (E) WILLIAMS (E) WILSON (L)	<u>A/T IND</u> BRAITMAN SALTZMAN  <u>PLANS</u> MCDONALD DUBE  <u>INFO</u> C. MILES <del>B. KING(RO)</del>
--	---	---	--	---

EXTERNAL DISTRIBUTION

<del>1 - LOCAL PDR Hartville, S. C.</del> <del>1 - DTIE(ABERNATHY)</del> <del>1 - NSIC(BUCHANAN)</del> 1 - ASLB(YORE/SAYRE/ WOODARD/"H" ST. <del>16 - CYS ACRS</del>	(1)(2)(10)-NATIONAL LAB'S 1-R.Schoonmaker, OC, GT, D-323 1-R. CATLIN, E-256-GT 1-CONSULTANT'S NEWMARK/BLUME/AGBABIAN 1-GERALD ULRIKSON...ORNL	1-PDR-SAN/LA/NY 1-GERALD LELLOUCHE BROOKHAVEN NAT. LAB 1-AGMED(WALTER KOESTER RM-C-427-GT 1-RD..MULLER..F-309 GT
---	--	---

Sent 8-25-73 to S. Teets for Dist.


Regulatory

File Cy.

#  
R R

TX NR 064

50-261



USAEC HQS GTWN

WU WSH

TLXA101 WAB093(1234)(2-002331E236)PD 07/24/73 1234

ICS IPMTZZ CSP

2033321351 TDMT HARTSVILLE SC 75 08-24 1234P EST

PMS JOHN F OLEARY DIRECTORATE OF LICENSING, DLR

US ATOMIC ENERGY COMMISSION

WASHINGTON DC 20545


ON 8/24/73 IT WAS DETERMINED THAT THE SETPOINT FOR HIGH STEAM  
FLOW SPECIFY IN TABLE 3.5-1 OF THE TECHNICAL SPECIFICATIONS  
WAS ABOVE ITS LIMIT THIS CONDITION WAS FOUND DURING A REVIEW  
OF SETPOINTS RECOMMENDED BY WESTINGHOUSE RECALIBRATION IS BEING  
INVESTIGATED AND THE NECESSARY CORRECTIONS WILL BE COMPLETED  
PRIOR TO 8/26/74

THE DETAILS OF THIS ABNORMAL OCCURANCE WILL BE REPORTED VIA  
LETTER WITHIN 10 DAYS

BENNY J FURR MANAGER H B ROBINSON SEG PLANT PO BOX 790 HARTSVILLE  
SC

252P

USAEC HQS GTWN



6475