

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:

Department of the Army, TACOM Life Cycle  
Management Command, Anniston Army Depot, AL  
and Marine Corps Logistics Base, Albany, GA

REPORT NUMBER(S) 14-002

2. NRC/REGIONAL OFFICE

Region III  
U. S. Nuclear Regulatory Commission  
2443 Warrenville Road, Suite 210  
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-38500

4. LICENSE NUMBER(S)

21-32838-01

5. DATE(S) OF INSPECTION

July 29 and 31, 2014

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- ☐ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.  
(Violations and Corrective Actions)

**Statement of Corrective Actions**

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Dennis Lawyer, Health Physicist, Region 1		8/29/14
BRANCH CHIEF	Aaron T. McCraw, Chief, MIB		8/22/14

**Docket File Information**

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:

Department of the Army, TACOM Life Cycle Management Command, Anniston Army Depot, AL and Marine Corps Logistics Base, Albany, GA

REPORT NUMBER(S) 14-002

2. NRC/REGIONAL OFFICE

Region III  
U. S. Nuclear Regulatory Commission  
2443 Warrenville Road, Suite 210  
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-38500

4. LICENSE NUMBER(S)

21-32838-01

5. DATE(S) OF INSPECTION

July 29 and 31, 2014

6. INSPECTION PROCEDURES USED

87126

7. INSPECTION FOCUS AREAS

03.01- 03.07

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S)

03124

2. PRIORITY

5

3. LICENSEE CONTACT

Thomas Gizicki, RSO

4. TELEPHONE NUMBER

(586) 282-0891

- ☐ Main Office Inspection      Next Inspection Date: July 2019
- ☒ Field Office Inspection    Anniston Depot and Marine Corps Logistics
- ☐ Temporary Job Site Inspection \_\_\_\_\_

**PROGRAM SCOPE**

This was a routine assist inspection conducted by Region I of the Army bases referenced above. The licensee exchanged self-luminous devices containing tritium on fire control devices, muzzle reference sensors and mortar sight units. Several thousand units were exchanged each year. The NRC license authorized the licensee to perform exchanges at various military bases located throughout the US. The licensee approved designated individuals to perform the exchange operations. The licensee performed contamination tests on the incoming devices. Units were serviced within a monitored fume hood. According to the RSO, the Department had not used licensed material under this license at its bases in Fort Bragg, North Carolina or the Blue Grass Army Depot in Richmond, Kentucky.

Anniston Army Depot: Licensee Contact, Anthony Phillips, 256-235-7544. Anniston Army Depot facility was equipped with five hoods for exchanging devices. The licensee approved six to eight individuals to perform this function. For future inspections note that the following address, 7 Frankford Avenue, Anniston, Alabama should be entered in a GPS device for directions to the visitor's entrance of the facility.

Marine Corps Logistics Base, Albany, Georgia: Licensee Contact, Terry Molargik, 229-639-5370. The licensee approved two people for exchanging operations. The licensee dedicated one hood for this activity. For future inspections note that the following address, 514 Radford Blvd, Albany, Georgia should be entered in a GPS device for directions to the visitor's entrance of the base.

No violations of NRC requirements were identified during this inspection.