

RE: CAROLINA POWER AND LIGHT COMPANY - H. B.  
ROBINSON NO. 2

W. C. Seidle, CO:II

X


I agree with your proposal as described in  
your memorandum dated December 29, 1969, that  
it is not necessary to plan for a special quality  
control inspection for the H. B. Robinson No. 2  
facility.

bcc: F. J. Nolan

Original Signed by  
E. J. Nolan

50-261

OFFICE ▶	Fm CO	Fm CO for			
SURNAME ▶	FJNolan:kbj	JPO'Reilly	J. P. O'Reilly, CO:HQ		1/14/70
DATE ▶	1/14/70	1/14/70			



UNITED STATES  
ATOMIC ENERGY COMMISSION  
DIVISION OF COMPLIANCE  
REGION II - SUITE 818  
230 PEACHTREE STREET, NORTHWEST  
ATLANTA, GEORGIA 30303

TELEPHONE: 526-4537

December 29, 1969

J. P. O'Reilly, Chief, Reactor Inspection and Enforcement Branch  
Division of Compliance, Headquarters

CAROLINA POWER AND LIGHT COMPANY (H. B. ROBINSON NO. 2), LICENSE NO.  
CPPR-26, DOCKET NO. 50-261

In accordance with PI 3800/2, Attachment N, Item 11, we have conducted a review of the previous inspection history for the subject facility and, from this review, we conclude that the inspection coverage to date meets the program standard required. We do not feel that a special quality control task force inspection would be necessary.

It is of interest to note that through the end of 1969, the Robinson 2 inspection effort has utilized the skills of 16 inspectors which resulted in 123 mandays of inspection. This does not include the time spent by inspectors participating in the Division vendor inspection program and attending Regulatory meetings at Headquarters, or by Headquarters personnel visiting the site.

We feel that it is significant to note that much of the Robinson 2 inspection effort has been performed by Region II construction specialists who have been a part of Headquarters directed QA/QC task forces in other regions; they are cognizant of the methods used by these special task forces.

The inspections to date have resulted in the completion of a large part of the requirements of PI 3800/2, and a continuation of the program is expected to complete the requirements in early 1970.

*IS/OR/Staff 1/8/70  
LK*

W. C. Seidle  
Senior Reactor Inspector

CO:II:WCS

cc: F. J. Long, CO:II  
J. C. Bryant, CO:II

9 3296