

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: EnergySolutions, LLC 1009 Commerce Park Drive, Suite 100, Oak Ridge, TN Locations Inspected: Bethesda and Silver Spring, MD REPORT NUMBER(S) 2014-001 and 2014-002		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713	
3. DOCKET NUMBER(S) 03038619	4. LICENSE NUMBER(S) 41-35044-01	5. DATE(S) OF INSPECTION 7/22-23/2014 (onsite) 7/31/2014 (add'l info) 8/15/2014 (exit)	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☐ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☒ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

1 Non-cited violation was discussed involving the following requirement(s) and corrective action(s):

License Condition 18.A of NRC License No. 41-35044-01, requires, in part, that EnergySolutions(ES) notify the NRC in writing at least 14 days before initiating activities at a temporary job site. On July 11, 2014, ES faxed in the notification to the NRC Region I Office as soon as ES identified the violation. However the notification indicated the work would begin on July 22, 2014; a time period less than 14 days. The notification should have been submitted no later than July 8, 2014. ES identified the violation, quickly faxed in the required notification, and followed up with a telephone call to the NRC inspector. ES placed the violation into their corrective action program and wrote a Condition Report on this matter to restore compliance and to prevent recurrence. ES's Radiation Safety Officer must be notified at least 30 days in advance and therefore will be able to notify the NRC in a timely manner. The inspector determined that the violation was not repetitive and not wilful. Based on the above information, the NRC has determined this to be a non-cited violation of License Condition 18.A.

- ☐ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	ARTHUR J. PALMER DIRECTOR, RADIOLOGICAL SVCS	<i>Arthur J. Palmer</i>	8/15/2014
NRC INSPECTOR	Kathy D. Modes, Sr. Health Physicist	<i>Kathy Modes</i>	8/15/2014
BRANCH CHIEF	Patricia A. Silva, Chief	<i>Patricia A. Silva</i>	8/15/14

*NRC FORM 591M PART 1 (07-2012) (RI Rev. 09/12/2013) G:\WordDocs\Current\Insp Record\IR41-35044-01.2014001and2.591MPt1.doc

SUNSI Review Completed By: / RA / K. Modes



Public



Non-Sensitive