

# CATEGORY 1

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9910290250      DOC. DATE: 99/10/21      NOTARIZED: NO      DOCKET #

FACIL: 50-269	Oconee Nuclear Station, Unit 1, Duke Power Co.	05000269
50-270	Oconee Nuclear Station, Unit 2, Duke Power Co.	05000270
50-287	Oconee Nuclear Station, Unit 3, Duke Power Co.	05000287
50-369	William B. McGuire Nuclear Station, Unit 1, Duke Power Co.	05000369
50-370	William B. McGuire Nuclear Station, Unit 2, Duke Power Co.	05000370
50-413	Catawba Nuclear Station, Unit 1, Duke Power Co.	05000413
50-414	Catawba Nuclear Station, Unit 2, Duke Power Co.	05000414

AUTH. NAME	AUTHOR AFFILIATION
TUCKMAN, M.S.	Duke Power Co.
RECIP. NAME	RECIPIENT AFFILIATION
	Records Management Branch (Document Control Desk)

SUBJECT: Requests use of encl Rev 2 to 97-GO-001 as alternative to ASME Boiler & Pressure Vessel Code, Section XI. NRC approval of original request was granted by NRC ltr & SER dtd 971015.

DISTRIBUTION CODE: A047D      COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 7

TITLE: OR Submittal: Inservice/Testing/Relief from ASME Code

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	HAWES, C	1   1	LABARGE, D	1   1
	RINALDI, F	1   1	TAM, P.	1   1
INTERNAL:	ACRS	1   1	<u>FILE CENTER</u> <u>01</u>	1   1
	NUDOCS-ABSTRACT	1   1	OGC/RP	1   0
	RES/DET/ERAB	1   1	RES/DET/MEB	1   1
EXTERNAL:	LITCO ANDERSON	1   1	NOAC	1   1
	NRC PDR	1   1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

TOTAL NUMBER OF COPIES REQUIRED: LTTR    13    ENCL    12



**Duke Power Company**  
*A Duke Energy Company*

EC07H  
526 South Church Street  
P.O. Box 1006  
Charlotte, NC 28201-1006

(704) 382-2200 OFFICE  
(704) 382-4360 FAX

**M. S. Tuckman**  
*Executive Vice President  
Nuclear Generation*

October 21, 1999

U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555-0001

Attention: Document Control Desk

Subject: Duke Energy Corporation

Oconee Nuclear Station, Units 1, 2, and 3  
Docket Nos. 50-269, 50-270, 50-287

McGuire Nuclear Station, Units 1 and 2  
Docket Nos. 50-369, 50-370

Catawba Nuclear Station, Units 1 and 2  
Docket Nos. 50-413, 50-414

Request to use an Alternative to the  
ASME Code, Section XI  
Duke Energy Corporation Serial Number 97-GO-001,  
Rev.2

TAC Nos. M99075, M99076, M99087, M99088, M99101,  
M99102, M991103

Attached is a Duke Energy Corporation request to use an alternative to the ASME Boiler and Pressure Vessel Code, Section XI. This request, Serial Number 97-GO-001, Rev.2 seeks NRC approval to use this alternative at Oconee, McGuire, and Catawba Nuclear Stations. Only Sections V and VII of this request have changed from Serial Number 97-GO-001, Rev.1. This request was originally submitted by a Duke letter to the NRC dated June 20, 1997 and revised by a Duke letter to the NRC dated August 7, 1997. NRC approval of this request was granted by NRC letter and safety evaluation dated October 15, 1997.

Duke Energy Corporation would like to initially implement this alternative during the End-of-Cycle Outage Number 10 on

9910290250 991021  
PDR ADDCK 05000269  
P PDR

000012

A04711

U. S. Nuclear Regulatory Commission

October 21, 1999

Page 2

Catawba Unit 2. In order to meet this schedule, it is requested that the NRC review and approve 97-GO-001, Rev.2 by February 7, 2000.

Please direct questions on this request to J. S. Warren at (704) 382-4986.

Very truly yours,



M. S. Tuckman

Attachments

xc w/att: L. A. Reyes, Regional Administrator  
U.S. Nuclear Regulatory Commission, Region II  
Atlanta Federal Center  
61 Forsyth St., SW, Suite 23T85  
Atlanta, GA 30303

D. E. Labarge, NRC Project Manager (ONS)  
U. S. Nuclear Regulatory Commission  
Mail Stop O-8 H12  
Washington, DC 20555-0001

F. Rinaldi, NRC Project Manager (MNS)  
U. S. Nuclear Regulatory Commission  
Mail Stop O-8 H12  
Washington, DC 20555-0001

P. S. Tam, NRC Project Manager (CNS)  
U. S. Nuclear Regulatory Commission  
Mail Stop O-8 H12  
Washington, DC 20555-0001

M. C. Shannon, NRC Senior Resident Inspector (ONS)  
S. M. Shaeffer, NRC Senior Resident Inspector (MNS)  
D. J. Roberts, NRC Senior Resident Inspector (CNS)

U. S. Nuclear Regulatory Commission

October 21, 1999

Page 3

bxc w/att:      L. B. Jones  
                  M. T. Cash  
                  J. W. Bryant  
                  K. L. Crane  
                  G. D. Gilbert  
                  L. J. Rudy  
                  K. E. Nicholson  
                  T. K. Pasour (2)  
                  L. E. Nicholson  
                  R. P. Todd  
                  J. E. Smith  
                  J. O. Barbour  
                  J. M. Boughman  
                  R. L. Gill  
                  J. S. Warren  
                  NRIA File/ELL

Attachment

DUKE ENERGY CORPORATION

Request for Alternative

ASME Boiler and Pressure Vessel Code, Section XI

**Background:**

Pursuant to 10 CFR 50.55a (a) (3) (i), Duke Energy Corporation requests the use of an alternative to the 1989 Edition of Section XI of the ASME Boiler and Pressure Vessel Code (Code) for Oconee Units 1, 2, and 3; McGuire Units 1 and 2; and Catawba Units 1 and 2.

The 1989 Edition of Section XI, (no addenda), paragraph IWA-5250(a)(2) states "if leakage occurs at a bolted connection, the bolting shall be removed, VT-3 visually examined for corrosion, and evaluated in accordance with IWA-3100." Duke Power Company previously requested, and was granted, NRC approval to use the 1990 Addenda as an alternative. The 1990 Addenda allows only the one bolt closest to the leak to be removed and visually examined for corrosion by a VT-3 inspector.

**I. Systems/Components for Which Alternative is Requested:**

All Class 1, 2, and 3 systems/components subject to IWA-5000 pressure testing.

**II. Code Requirement:**

Section XI of the ASME Code, 1989 Edition with 1990 Addenda, Subsection IWA-5250(a)(2) states: "If leakage occurs at a bolted connection, one of the bolts shall be removed, VT-3 examined, and evaluated in accordance with IWA-3100. The bolt selected shall be the one closest to the source of leakage. When the removed bolt has evidence of degradation, all remaining bolting in the connection shall be removed, VT-3 examined, and evaluated in accordance with IWA-3100."

**III. Requirement for Which Alternative Is Requested:**

Relief is requested from the mandatory requirement to remove the bolt closest to the source of leakage when leakage is detected at a mechanical connection.

**IV. Basis for Requesting Alternative:**

Removal of pressure retaining bolting at mechanical connections for visual, VT-3 examination and subsequent evaluation, in locations where leakage has been identified, is not always the most discerning course of action to determine the acceptability of the bolting. The Code requirement to remove, examine, and evaluate bolting in this situation does not allow the owner to consider other factors which may indicate the acceptability of mechanical joint bolting.

Other factors which should be considered when evaluating bolting acceptability when leakage has been identified at a mechanical joint include, but are not limited to: joint bolting material, service age of joint bolting materials, location of the leakage, history of leakage at the joint, evidence of corrosion with the joint assembled, and corrosiveness of process fluid.

Performance of the pressure test while the system is in service may identify leakage at a bolted connection that, upon evaluation, may conclude the integrity and pressure retaining ability of the joint is not challenged. It would not be prudent to negatively impact the availability of a safety system by removing the system from service to address a leak that does not challenge the system's ability to perform its safety function.

A situation frequently encountered at Duke Energy Corporation is the complete replacement of bolting materials (studs, bolts, nuts, washers, etc.) at mechanical joints during plant outages. When the associated system piping is pressurized during plant start up, leakage may be identified at these joints. The root cause of this leakage is most often due to thermal expansion of the piping and bolting materials at the joint and subsequent fluid seepage at the joint gasket. Proper retorquing of the joint bolting, in most cases, stops the leakage. Removal of the joint bolting to evaluate for corrosion would be unwarranted in this

situation due to the new condition of the bolting materials.

#### **V. Alternative Examinations:**

When leakage is identified at bolted connections by Visual, VT-2 examination during system pressure testing, an evaluation will be performed to determine the susceptibility of the bolting to corrosion and assess the potential for failure. The evaluation will, at a minimum, consider the following factors:

1. Bolting materials
2. Corrosiveness of process fluid leaking
3. Leakage location
4. Leakage history at connection or other system components
5. Visual evidence of corrosion at connection (while connection is assembled)
6. Service age of bolting materials

When the evaluation of the above variables is concluded and the evaluation determines that the leaking condition has not degraded the fasteners, then no further action is necessary. However, reasonable attempts to stop the leakage shall be taken.

If the evaluations of the variables above indicate the need for further evaluation, or no evaluation is performed, then a bolt closest to the source of leakage shall be removed and VT-3<sup>1</sup> visually examined. When the removed bolting shows evidence of rejectable degradation, all remaining bolts in the connection shall be removed and VT-3 visually examined. If the leakage is identified when the bolted connection is in service or Technical Specifications require to be operable, and the information in the evaluation is supportive, the removal of the bolt for VT-3 visual examination may be deferred to the next component/system outage of sufficient duration.

---

<sup>1</sup> The acceptance criteria for Visual, VT-1 will be used to assess the acceptability of the bolting.

**VI. Justification for Granting Alternative:**

The purpose of the Code required corrective action to remove bolts and visually examine them for degradation, as stated in IWA-5250(a)(2), is to ensure joint integrity. In addition to removing bolts and performing a Visual, VT-3 examination, Section V above states alternative methods to ensure joint integrity of bolted connections. These alternative methods have been determined to provide an acceptable level of quality and safety.

**VII. Implementation Schedule:**

Catawba Unit 2 is currently scheduled to begin refueling outage EOC10 on March 11, 2000. Duke Energy Corporation requests that approval be granted to permit use of this alternative examination at that time.