

2015 PALISADES NUCLEAR PLANT
INITIAL LICENSE RETAKE EXAMINATION
EXAM HANDOUTS PROVIDED FOR CANDIDATE

- ① ~~A~~ B C D
- ② A B C D
3. A B C D
- ④ A B C D
5. A B C D
6. A B C D
- ⑦ A B C D
8. A B C D
9. A B C D
10. A B C D
11. A B C D
12. A B C ~~D~~
- ⑬ A B C D
14. A B C D
- ⑮ ~~A~~ B C D
- ⑯ A B C D
- ⑰ A B C D
- ⑱ A B C ~~D~~
- ⑲ A B C D
20. A B C D
21. A B C D
- ⑳ A B C D
- ㉓ A B C D
24. A B C D
25. A B C D

$$\frac{21}{25} = 84\%$$

1/21/2015 25Q PAL SRO WRITTEN RETAKE EXAMINATION HANDOUTS:

- ORM (Operating Requirements Manual) Section 3.17.6, pages 15-18 of 33
- EOP 4.0 (Loss of Coolant Accident Recovery) Safety Function Status Checks, Attachment 1, pages 1-15
- EAL Wall Charts (directory EIPs, SEP Supplement 1 for MERLIN)

EXAM ANALYSIS

Q1: Vapor Space LOCA RV-1039 open

Incorrectly assumed RV was reseated

EOP 4.0 Step 10f has guidance to depressurize to reseal RV.

Conclusion: Misread or read too quickly the question/answers

Q12: Missed SIAS actuated which deenergizes 'E' bus, so NO heaters energized

Conclusion: Misread or read too quickly the question/answers

Q15: Missed the fact that Containment Integrity was lost which requires locking closed Cont. Isolation valves.

Conclusion: Misread or read too quickly the question/answers AND/OR Misunderstood the concept.

Q18: Assumed it was necessary to improve subcooling before Natural Circulation could be improved

Conclusion: Misunderstood the concept.

Overall Conclusion: No Training weaknesses in the Program so no changes to questions.

* No Post Exam comments or challenges from candidate.

FRONT

CLASSROOM 'L'

PROCTOR

DOOR

Applicant

DOOR

**PALISADES 2015 NRC WRITTEN
EXAM SEATING CHART**

SKO Retake Exam
Finish 1056

Start 0900

Q: 7: Is 63% level actual or indicated?

A: Actual

Q: 13: Is VCT level assumed to be stable?

A: Do your best with the information given.

Applicant Questions + Proctor Response

* No Post Exam Comments or Challenges.

Jan 2015
RECEIVED DEC 28 2015