

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Lochmueller Group, Inc.
6200 Vogel Rd
Evansville, IN 47715-40006

REPORT NUMBER(S) 15-01

2. NRC/REGIONAL OFFICE

Region III
U. S. Nuclear Regulatory Commission
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-30449

4. LICENSE NUMBER(S)

13-25890-01

5. DATE(S) OF INSPECTION

4/13/2015

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

_____ Non-cited violation(s) were discussed involving the following requirement(s):

- ☐ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	E.L. Kulzer	<i>E.L. Kulzer</i>	4/22/15
BRANCH CHIEF	A.T. McCraw	<i>ATM for ATM</i>	4/27/15

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Lochmueller Group, Inc.
6200 Vogel Rd
Evansville, IN 47715-40006

REPORT NUMBER(S) 15-01

2. NRC/REGIONAL OFFICE

Region III
U. S. Nuclear Regulatory Commission
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-30449

4. LICENSE NUMBER(S)

13-25890-01

5. DATE(S) OF INSPECTION

4/13/2015

6. INSPECTION PROCEDURES USED

IP 87121

7. INSPECTION FOCUS AREAS

03.01 through 03.07

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S)

2201

2. PRIORITY

5

3. LICENSEE CONTACT

Dan Farvardin

4. TELEPHONE NUMBER

(812) 479-6200



Main Office Inspection

Next Inspection Date: 04/13/2020



Field Office Inspection



Temporary Job Site Inspection

PROGRAM SCOPE

This was a routine inspection of an engineering firm. At the time of the inspection, the Radiation Safety Officer was out of the country. The licensee possessed six Troxler Model 3400 moisture density gauges for use during the construction season (May-November) for soils engineering projects. The licensee does not perform any service or maintenance activities on its gauges; these services are performed by the manufacturer. The licensee employed six authorized gauge users who have completed manufacturers training. The licensee stored its gauges in a vault in the licensee's office in Evansville, Indiana.

Performance Observations

At the time of this inspection, a gauge was in use in Evansville, Indiana, but the inspector could find no contractors working at the site. One of the authorized gauge users interviewed by the inspector possessed required shipping papers that contained all appropriate information and were accessible in the transport vehicle. The licensee locked and chained its gauges to the rear of the vehicle during transport. The authorized gauge user demonstrated an adequate level of understanding of emergency and handling procedures during interviews. Security during transport was described with no problems noted. The inspector reviewed other program areas which included dosimetry, 20.1101 audits, leak tests, inventory checks, and survey instrument availability.

No violations of NRC requirements were identified during the inspection.