

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9801280150	DOC. DATE: 98/01/21	NOTARIZED: NO		DOCKET #
FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.				05000269
50-270 Oconee Nuclear Station, Unit 2, Duke Power Co.				05000270
50-287 Oconee Nuclear Station, Unit 3, Duke Power Co.				05000287

AUTH. NAME	AUTHOR AFFILIATION
MCCOLLUM, W.R.	Duke Power Co.
RECIP. NAME	RECIPIENT AFFILIATION
	Document Control Branch (Document Control Desk)

SUBJECT: Submits request to RAI re response to violations noted in
 insp repts 50-269/97-14, 50-270/97-14 & 50-287/97-14, per
 980107 telcon & 980108 ltr.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 3
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR	ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR	ENCL
PD2-2 PD	1	1	LABARGE, D	1	1
INTERNAL: ACRS	2	2	AEOD/SPD/RAB	1	1
AEOD/TTC	1	1	DEDRO	1	1
FILE CENTER	1	1	NRR/DRCH/HHFB	1	1
NRR/DRPM/PECB	1	1	NRR/DRPM/PERB	1	1
NUDOCS-ABSTRACT	1	1	OE DIR	1	1
OGC/HDS2	1	1	RGN2 FILE 01	1	1
INTERNAL: LITCO BRYCE, J H	1	1	NOAC	1	1
NRC PDR	1	1	NUDOCS FULLTEXT	1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS
 OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL
 DESK (DCD) ON EXTENSION 415-2083

TOTAL NUMBER OF COPIES REQUIRED: LTTR 19 ENCL 0

C
A
T
E
G
O
R
Y

1

D
O
C
U
M
E
N
T



Duke Power Company
A Duke Energy Company

Oconee Nuclear Site
P.O. Box 1439
Seneca, SC 29679

W. R. McCollum, Jr.
Vice President

(864) 885-3107 OFFICE
(864) 885-3564 FAX

January 21, 1998

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555

Subject: Oconee Nuclear Site
Docket Nos. 50-269, -270, -287
Inspection Report 50-269, -270, -287/97-14
Reply to Notices of Violation

Gentlemen:

By letter dated December 17, 1997, Duke Energy Corporation (Duke) responded to eight Notices of Violation as described in Inspection Report No. 50-269/97-14, 50-270/97-14, and 50-287/97-14.

Duke's response to Violation 97-14-04 addressed the failure to implement a vendor recommendation for DB-25 circuit breakers as a procedural oversight. Based on a request in a phone conversation on January 7, 1998, and a letter dated January 8, 1998, Duke provides the following additional information concerning corrective actions.

Procedure IP/0/A/2001/003B is one of seven preventative maintenance procedures (IPs) related to QA-1 metalclad (600V/4K/7KV), air, and switchyard power circuit breakers that were reviewed and rewritten in 1995 to conform with the Appendix F (Procedure Upgrade Process) of the Nuclear Production Department (NPD) Procedure Development Guide and to meet Nuclear System Directive (NSD) 703, "Preparation of Procedure" requirements. Vendor instruction books, as well as industry guidance, were referenced in these procedures. A re-review of these seven procedures against the associated vendor instruction books concluded that the procedures are technically acceptable as written and that no critical vendor maintenance information has been omitted. The problem identified in IP/0/A/2001/003B is considered an isolated case.

9801280150 980121
PDR ADOCK 05000269
G PDR




NRC Document Control Desk
January 21, 1998
Page 3

bcc: B. L. Peele
M. K. Nazar
W. W. Foster
D. B. Coyle
P. R. Newton
C. A. Little
T. D. Curtis
R. L. Dobson
J. E. Burchfield
L. A. Keller - G.O.
M. S. Kitlan - CNS
M. T. Cash - MNS
J. E. Smith
ELL - EC050
NSRB - EC05N
NRC Commitments

NRC Document Control Desk
January 21, 1998
Page 2

If there are any questions or further information is needed,
you may contact Ed Burchfield at (864) 885-3292.

Very truly yours,



W. R. McCollum, Jr.,
Site Vice President

cc: Mr. L. A. Reyes, Regional Administrator
U. S. Nuclear Regulatory Commission, Region II

Mr. D. E. LaBarge, Project Manager
Office of Nuclear Reactor Regulation

Mr. M. A. Scott
Senior Resident Inspector
Oconee Nuclear Site