

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED: Heller and Johnsen Foot of Broad Street Stratford, Connecticut 06615  REPORT NUMBER(S) 2015001		2. NRC/REGIONAL OFFICE  U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713	
3. DOCKET NUMBER(S) 03033138	4. LICENSE NUMBER(S) 06-30033-01	5. DATE(S) OF INSPECTION February 5, 2015 – April 28, 2015	

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☐ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s) and corrective action(s):




- ☒ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)

10 CFR 20.2201(a)(i) requires, in part, that each licensee report by telephone, immediately after its occurrence becomes known to a licensee, any lost, stolen, or missing licensed material in an aggregate quantity equal to or greater than 1,000 times the quantities in appendix C to part 20.

Contrary to the above, from January 16, 2015, until February 5, 2015, the licensee did not report by telephone, immediately after its occurrence became known to the licensee, any lost, stolen, or missing material in an aggregate quantity equal to or greater than 1,000 times the quantities in appendix C to part 20. Specifically, the licensee did not notify the NRC of a device that was stolen and recovered on January 16, 2015, until questioned by an NRC inspector on February 5, 2015. The device contained material greater than 1,000 times appendix C to part 20.

**Statement of Corrective Actions**

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	LAWRENCE F. JOHNSEN		4-28-15
NRC INSPECTOR	Michael Reichard		4/29/15
BRANCH CHIEF	Blake Welling		4/28/15