



June 9, 2015

NG-15-0212

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

Duane Arnold Energy Center
Docket No. 50-331
Renewed Op. License No. DPR-49

NextEra Energy Duane Arnold, LLC Readiness for 95001 Supplemental Inspection

Reference: NRC letter, EA-14-237, Final Significance Determination of a White Finding With Assessment Followup and Notice of Violation; NRC Inspection Report No. 05000331/2015010; dated April 16, 2015 (ML 15050A653)

In the above reference, the Nuclear Regulatory Commission (NRC) issued a white finding to NextEra Energy Duane Arnold, LLC (hereafter NextEra Energy Duane Arnold), for a finding involving delamination of the coating inside the torus. The reference also indicates that the NRC will conduct a supplemental inspection using Inspection Procedure 95001, "Inspection for One or Two White Inputs in a Strategic Performance Area," upon being notified of NextEra Energy Duane Arnold's readiness for inspection.

NextEra Energy Duane Arnold has completed investigations to determine the root and contributing causes of the performance issues associated with the white finding. The extent of condition and extent of cause have also been evaluated, and corrective actions have been developed to address the root and contributing causes and to prevent recurrence of the significant performance issues. NextEra Energy Duane Arnold believes the corrective actions taken and planned will address the issues and provide the basis for sustained, improved performance at Duane Arnold Energy Center.

NextEra Energy Duane Arnold is notifying the NRC of readiness for the 95001 supplemental inspection.

IEOI
NRR

If you have any questions, please contact J. Michael Davis at (319) 851-7032.

This letter contains no new regulatory commitments.



T. A. Vehec
Vice President, Duane Arnold Energy Center
NextEra Energy Duane Arnold, LLC

cc: Administrator, Region III, USNRC
Project Manager, DAEC, USNRC
Senior Resident Inspector, DAEC, USNRC