



Entergy Operations, Inc.

River Bend Station  
5485 U.S. Highway 61N  
St. Francisville, LA 70775  
Tel 225-381-4157

**N. Todd Brumfield**

Director-Performance Improvement  
& Regulatory Assurance

July 30, 2015

Mr. Greg Warnick  
U. S. Nuclear Regulatory Commission  
Region IV  
1600 E. Lamar Blvd.  
Arlington, TX 76011-4511

RBG-47599  
RBF1-15-0122

Reference: NRC Letter to Entergy, dated July 7, 2015, NRC Inspection Report  
05000458/2015009, Preliminary White Finding

Subject: Response to Preliminary White Finding  
River Bend Station – Unit 1  
Docket No. 50-458  
License No. NPF-47

Dear Mr. Warnick:

As requested in NRC Special Inspection Report 05000458/2015009, this letter is to inform the NRC of our intentions regarding the Preliminary White Finding for failure to maintain the simulator consistent with actual plant response for normal and transient conditions related to feedwater flows, alarm response, and behavior of the startup feedwater regulating valve controller. River Bend agrees with the performance deficiency and violation.

Should you have any questions regarding this matter, please contact Mr. Joey Clark at (225) 381-4177.

A handwritten signature in black ink, appearing to read 'N. Todd Brumfield', is written over the typed name.

NTB/KRH

cc: U.S. Nuclear Regulatory Commission  
Region IV  
1600 E. Lamar Blvd.  
Arlington, TX 76011-4511

NRC Resident Inspector  
PO Box 1050  
St. Francisville, LA 70775

Ms. Tracie Lowrey  
Public Utility Commission of Texas  
1701 N. Congress Ave.  
Austin, TX 78711-3326

Mr. Alan Wang, Project Manager  
U.S. Nuclear Regulatory Commission  
MS O-8B1  
11555 Rockville Pike  
Rockville, MD 20852-2738

ADAMS ACCESSION NUMBER: ML15216A612