

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Benefis Hospital
1101 26th Street South
Great Falls, MT 59405

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region IV, 1600 East Lamar Blvd
Arlington, Texas 76011-4511

REPORT NO:

2015-001

3. DOCKET NUMBER

030-02404

4. LICENSE NUMBER

25-12710-01

5. DATE OF INSPECTION

June 25, 2015

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☐ 1. Based on the inspection findings, no violations were identified.
- ☒ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.
- ☐ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- ☒ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

License Condition 13.A requires that sealed sources shall be tested for leakage and/or contamination at intervals specified by a certificate of registration issued by the NRC on an agreement state. (Typically 6-months).

Contrary to the above, the licensee failed to perform leak tests of a Cs-137 sealed source, #469, in a Shepherd Calibrator since 8/9/2007.

The licensee immediately performed a leak test of the source.

Licensee's Statement of Corrective Actions for Item 4, above.

No leakage detected

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Greg Hilpert	<i>Greg Hilpert</i>	6/25/15
NRC INSPECTOR	Don Stearns	<i>Donald Stearns</i>	6/25/15
BRANCH CHIEF	G.M. Vasquez	<i>GM Vasquez</i>	7/20/2015