

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Pharmalogic MT, Inc.
4404 Expressway Road
Missoula, Montana

REPORT NO: 030-38401/2015-001

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region IV, 1600 East Lamar Blvd
Arlington, Texas 76011-4511

3. DOCKET NUMBER

030-38401

4. LICENSE NUMBER

09-29398-01MD

5. DATE OF INSPECTION

June 18 – July 23, 2015

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violations(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.

☐ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- ☐ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTORS	Rick Muñoz Jason Dykert	/RA/ <i>Jason Dykert</i>	7/23/2015
BRANCH CHIEF	<i>G M Vasquez</i>	<i>G M Vasquez</i>	8/5/15

☐ Non-Public ☐ Sensitive – Security-Related

☒ Public

☒ Non-Sensitive

Dykert, Jason

From: Dykert, Jason
Sent: Friday, July 24, 2015 9:05 AM
To: 'tscheidel@pharmalogic.info'
Cc: Munoz, Rick
Subject: NRC Inspection Report 030-38401/2015-001
Attachments: Pharmalogic 591M Part1 Inspection Report.pdf

TJ,

Attached is the inspection report I discussed with you on the phone during the exit meeting on July 23, 2015, referencing the inspection conducted at 4404 Expressway Road in Missoula, MT.

The inspection purpose was to examine activities you conduct under your NRC License (09-29398-01MD) as they relate to safety, security and compliance with the Commission's rules and regulations.

If you have any questions regarding the report or inspection, please feel free to contact me.

Jason C Dykert
Health Physicist, Inspection Branch
US NRC, Region IV
(817) 200 - 1427

