

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8709290146 DOC. DATE: 87/09/17 NOTARIZED: NO DOCKET #  
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co. 05000269  
 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co. 05000270  
 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co. 05000287  
 AUTH. NAME AUTHOR AFFILIATION  
 TUCKER, H. B. Duke Power Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 GRACE, J. N. Region 2, Office of Director

SUBJECT: Advises that util in process of preparing & reviewing  
 response to NRC 870818 request for addl info re IE Bulletin  
 85-003, "Motor-Operated Valve Common Mode Failure During  
 Plant Transient." Response will be submitted by 871015.

DISTRIBUTION CODE: IE11D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: Bulletin Response (50 DKT)

NOTES: AEOD/Ornstein:1cy. 05000269  
 AEOD/Ornstein:1cy. 05000270  
 AEOD/Ornstein:1cy. 05000287

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD2-3 LA	1 0	PD2-3 PD	1 1
PASTIS, H	1 1		
INTERNAL: AEOD/DOA	1 1	AEOD/DSP	1 1
AEOD/DSP/TPAB	1 1	NRR/DEST/ADE	1 1
NRR/DEST/ADS	1 1	NRR/DEST/MEB	1 1
NRR/DOEA/EAB	1 1	NRR/DOEA/GCB	1 1
NRR/DREP/EPB	1 1	NRR/PMAS/ILRB	1 1
<del>REG-FILE</del> 02	1 1	RES/DE/EIB	1 1
RGN2 FILE 01	1 1		
EXTERNAL: LPDR	1 1	NRC PDR	1 1
NSIC	1 1		
NOTES:	1		

TOTAL NUMBER OF COPIES REQUIRED: LTTR 20 ENCL 0

DUKE POWER COMPANY

P.O. BOX 33189

CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

TELEPHONE  
(704) 373-4531

87 SEP 23 A10: 57

September 17, 1987

Dr. J. Nelson Grace, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323


Subject: Oconee Nuclear Station  
Docket Nos. 50-269, -270, -287  
Request for Additional Information Concerning  
Oconee's Response to IE Bulletin 85-03

Dear Sir:

By letter dated August 18, 1987 the NRC Staff requested additional information to continue their review of Duke Power Company's response to IE Bulletin 85-03, "Motor Operated Valve Common Mode Failure During Plant Transient Due to Improper Switch Settings". A response for additional information was requested within 30 days.

Duke Power Company is currently in the process of preparing and reviewing its response to the request for additional information. It is anticipated that a response will be provided no later than October 15, 1987.

Very truly yours,



Hal B. Tucker

MAH/77/sbn

Attachment

xc: Mr. J. C. Bryant  
NRC Resident Inspector  
Oconee Nuclear Station

Ms. Helen Pastis  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, D. C. 20555

8709290146 870917  
PDR ADOCK 05000269  
Q PDR

U.S. NRC - REGION 2  
OFFICIAL COPY

IE11