

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9004270292 DOC. DATE: 90/04/10 NOTARIZED: NO DOCKET #
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co. 05000269
 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co. 05000270
 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co. 05000287
 AUTH. NAME AUTHOR AFFILIATION
 TUCKER, H.B. Duke Power Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Requests extension of completion of all corrective actions
 from 900401 to 901015.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 01
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-3 PD	1 1	WIENS, L	1 1
INTERNAL:	ACRS	2 2	AEOD	1 1
	AEOD/DEIIB	1 1	AEOD/TPAD	1 1
	DEDRO	1 1	NRR SHANKMAN, S	1 1
	NRR/DLPQ/LPEB10	1 1	NRR/DOEA DIR 11	1 1
	NRR/DREP/PEPB9D	1 1	NRR/DRIS/DIR	1 1
	NRR/DST/DIR 8E2	1 1	NRR/PMAS/ILRB12	1 1
	NUDOCS-ABSTRACT	1 1	<u>OE DIR</u>	1 1
	OGC/HDS2	1 1	<u>REG FILE</u> 02	1 1
	RES/DSR/HFB/HFS	1 1	RGN2 FILE 01	1 1
EXTERNAL:	LPDR	1 1	NRC PDR	1 1
	NSIC	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL 24-0

Duke Power Company
P.O. Box 33198
Charlotte, N.C. 28242

Hal B. Tucker
Vice President
Nuclear Production
(704)373-4531



DUKE POWER

April 10, 1990

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Subject: Oconee Nuclear Station
Docket Nos. 50-269, -270, -287
Inspection Report Nos. 50-269, -270, -287/89-25

Gentlemen:

By a letter dated October 9, 1990, I had provided a written response to a notice of violation that was identified within Inspection Report 50-269, -270, -287/89-25. In my response to part A of the violation I had committed to completing all of my corrective actions by April 1, 1990. Please be advised that this date needs to be changed by October 15, 1990. The additional time is required to complete all of the necessary revisions to affected station directives. The reason for this is due to the need to allocate the available resources to higher priority tasks, such as preparation for the upcoming Unit 1 refueling outage.

If you have any questions regarding this issue please do not hesitate to contact us through the normal licensing channels.

Very truly yours,

H. B. Tucker

PFG105/td

cc: Mr. S. D. Ebnetter, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, GA 30323

Mr. P. H. Skinner
NRC Resident Inspector
Oconee Nuclear Station

Mr. L. A. Wiens
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, DC 20555

9004270292 900410
PDR ADDCK 05000269
Q PDC

IE01
40