

## CONVERSATION RECORD

NAME OF PERSON(S) CONTACTED OR IN CONTACT WITH YOU	DATE OF CONTACT	TYPE OF CONVERSATION	
Lawrence Pitt	07/21/2015	<input type="checkbox"/> E-MAIL	<input type="checkbox"/> INCOMING
E-MAIL ADDRESS	TELEPHONE NUMBER	<input checked="" type="checkbox"/> TELEPHONE	<input type="checkbox"/> OUTGOING
lpmanisotech@gmail.com	(806) 745-3300		
ORGANIZATION	DOCKET NUMBER(S)		
Positron Corp.	030-38150		
LICENSE NUMBER(S)	CONTROL NUMBER(S)		
13-32765-01	585899		

## SUBJECT

Additional information needed after review of the licensee's April 29, 2015, response to the March 25, 2015, request for additional information.

## SUMMARY AND ACTION REQUIRED (IF ANY)

I noted that in Mr. Pitt's April 29 response, he had not yet received the results of leak tests that were performed on the sources that were transferred from the Fishers, Indian location. Mr. Pitt stated that the sources were leak tested and that the results were being forwarded to him.

I informed Mr. Pitt that failure to leak test the sources before transfer is an apparent violation of license condition 17.D. Mr. Pitt understood and confirmed that the sources were not leak tested when they were removed from storage for transfer by ADCO services. He stated that Positron contracted with ADCO for the disposal of the sources, and that Positron had expected that ADCO would do the leak testing before the sources were transferred. The sources were transferred to RAM Services in Two Rivers, WI. RAM Services has conducted the leak tests after receipt of the sources from ADCO at the request of Positron. The results were being forwarded to Positron.

In addition to submitting the results of leak tests, I requested that Mr. Pitt also submit the following:

1. Provide the date that each source was placed in storage.
2. Provide the date when they were removed from storage for transfer.
3. Provide the date when they were last leak tested by Positron.
4. Verify the make, model number, activity, and isotope of each source that was transferred by ADCO.

After reviewing a record for the Fishers, Indiana, facility of a sealed source inventory conducted by Nick Overman in September 2014, we noted that Positron possessed a 0.1107 microcurie Cs-137 source, RadQual model BM08-37. This model number was never listed on the license. Please address this issue. If the source was possessed as a generally license source, please submit evidence that it was received and possessed as such. If it is a specifically licensed item, then it should have been listed on the license. Possession of a specifically licensed source that is not authorized on an NRC license is a potential violation.

Mr. Pitt also informed me that Mr. Joe Oliverio is the current President for Positron, and Mr. Corey Conn is the CFO. Mr. Pitt stated that Mr. Conn was aware of the ongoing issue with the NRC license, and that he will advise both Mr. Oliverio and Mr. Conn of the potential violation.

CONVERSATION RECORD (continued)

LICENSE NUMBER(S)

13-32765-01

CONTROL NUMBER(S)


585899

SUMMARY AND ACTION REQUIRED (IF ANY) (Continued)

NAME OF PERSON DOCUMENTING CONVERSATION

Kevin Null

SIGNATURE



DATE OF SIGNATURE

07/21/2015