

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9505180585 DOC. DATE: 95/05/04 NOTARIZED: NO DOCKET #
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co. 05000269
 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co. 05000270
 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co. 05000287

AUTH. NAME AUTHOR AFFILIATION
 HAMPTON, J.W. Duke Power Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Corrects error in 950309 ltr, summarizing commitments made during 950224 meeting re outstanding issues associated w/SWS operational performance insp, finding 7, part f concerning trench covers.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 PD	1	WIENS, L	1
INTERNAL:	ACRS	2	AEOD/DEIB	1
	AEOD/SPD/RAB	1	AEOD/TTC	1
	DEDRO	1	<u>FILE CENTER</u>	1
	NRR/DISP/PIPB	1	NRR/DORS/OEAB	1
	NRR/DRCH/HHFB	1	NUDOCS-ABSTRACT	1
	OE DIR	1	OGC/HDS2	1
	RGN2 FILE 01	1		
EXTERNAL:	LITCO BRYCE, J H	1	NOAC	1
	NRC PDR	1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2083) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 19 ENCL 0

MAY

Duke Power Company
Oconee Nuclear Site
P.O. Box 1439
Seneca, SC 29679

J. W. HAMPTON
Vice President
(803)885-3499 Office
(803)885-3564 Fax



DUKE POWER

May 4, 1995


U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Subject: Oconee Nuclear Station, Units 1, 2 and 3
Docket Nos. 50-269, -270 and -287
Commitments from February 24, 1995 Service Water
Meeting

Our letter dated March 9, 1995 summarized commitments made during our February 24, 1995 meeting with the NRC regarding outstanding issues associated with the Service Water System Operational Performance Inspection (SWSOPI). The March 9, 1995 letter contained a minor error.

Regarding the Inspection Report 93-25 cover letter, Finding #7, part f, the March 9, 1995 letter stated that the trench covers have been bolted down per OE-6596. The trench covers were not actually bolted down per this minor modification. Instead, the covers were modified so that they will not fall into the trench after a seismic event provided that they are positioned properly in place. Also, the covers were stenciled with a warning which communicates the importance of ensuring that the covers are positioned properly in place. We apologize for any inconvenience caused by this error.

Very truly yours,



J. W. Hampton
Site Vice President
Oconee Nuclear Station

cc: Mr. L. A. Wiens
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. S. D. Ebnetter
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta St., NW, Suite 2900
Atlanta, GA 30323

9505180585 950504
PDR ADDCK 05000269
Q PDR

1-FO
1/0

U. S. Nuclear Regulatory Commission
May 4, 1995
Page 2

Mr. P. E. Harmon
Senior NRC Resident Inspector
Oconee Nuclear Station