

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9610220320 DOC. DATE: 96/10/10 NOTARIZED: NO
 FACIL: 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co.
 AUTH. NAME AUTHOR AFFILIATION
 HAMPTON, J.W. Duke Power Co.
 RECIP. NAME RECIPIENT AFFILIATION

DOCKET #
05000270

SUBJECT: LER 96-003-00 has been canceled.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

| | RECIPIENT ID CODE/NAME | COPIES LTTR ENCL | RECIPIENT ID CODE/NAME | COPIES LTTR ENCL |
|-----------|---------------------------|---------------------|---------------------------|---------------------|
| | PD2-2 PD | 1 | LABARGE, D | 1 |
| INTERNAL: | ACRS | 1 | AEOD/SPD/RAB | 2 |
| | AEOD/SPD/RRAB | 2 | <u>FILE CENTER</u> | 1 |
| | NRR/DE/ECGB | 1 | NRR/DE/EELB | 1 |
| | NRR/DE/EMEB | 1 | NRR/DRCH/HHFB | 1 |
| | NRR/DRCH/HICB | 1 | NRR/DRCH/HOLB | 1 |
| | NRR/DRCH/HQMB | 1 | NRR/DRPM/PECB | 1 |
| | NRR/DSSA/SPLB | 1 | NRR/DSSA/SRXB | 1 |
| | RES/DSIR/EIB | 1 | RGN2 FILE 01 | 1 |
| EXTERNAL: | L ST LOBBY WARD | 1 | LITCO BRYCE, J H | 1 |
| | NOAC MURPHY, G.A | 1 | NOAC POORE, W. | 1 |
| | NRC PDR | 1 | NUDOCS FULL TXT | 1 |

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 26 ENCL 26

C
A
T
E
G
O
R
Y

1

D
O
C
U
M
E
N
T

Duke Power Company
Oconee Nuclear Site
P.O. Box 1439
Seneca, SC 29679

J. W. HAMPTON
Vice President
(864)885-3499 Office
(864)885-3564 Fax



DUKE POWER

October 10, 1996

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Subject: Oconee Nuclear Site
Docket Nos. 50-269, -270, -287
LER 270/96-03


Gentlemen:

Licensee Event Report 270/96-03, "Pressurizer Relief Valve Technically Inoperable", was submitted on August 19, 1996. Further Engineering analysis has determined that this event is not reportable and the Licensee Event Report is not required.

During the initial report, Oconee Nuclear Station indicated that 2RC-67 (Pressurizer Relief Valve on Unit 2) failed to meet its as found set pressure band. After further analysis, it was concluded that 2RC-67 would have performed its intended safety function. Therefore, this valve has been determined to be past operable.

In light of this information, Duke Power Company has determined the event is not reportable per 10 CFR 50.73 and would like to rescind Licensee Event Report 270/96-03 and the commitments contained within the report.

Very truly yours,


J. W. Hampton
Vice President

9610220320 961010
PDR ADOCK 05000270
S PDR

TE2210

Document Control Desk
October 10, 1996

Page Two

cc: Mr. S. D. Ebnetter
Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta St., NW, Suite 2900
Atlanta, GA 30323

Mr. D. E. LaBarge
U. S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Washington D.C. 20555

INPO Records Center
700 Galleria Parkway
Atlanta, GA 30339-5957

Mr. M. Scott
NRC Resident Inspector
Oconee Nuclear Station