

Security-Related Information - Withhold Under 10 CFR 2.390



August 27, 2015

SBK-L-15160

Docket No. 50-443

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555-0001

Seabrook Station  
Reply to Inspection Report 05000443/2014403

Reference:

NRC letter "Seabrook Station, Unit No. 1 – NRC Security Inspection Report  
05000443/2014403," November 20, 2014

The referenced Inspection Report (IR) discusses three 10 CFR 73.54 violations and one licensee identified violation of very low safety significance at Seabrook Station. As discussed in the IR, the NRC has exercised enforcement discretion for these violations in accordance with the Security Issues Forum Charter. Further, the IR requests NextEra Energy Seabrook, LLC (NextEra) notify the NRC of the date that compliance for these violations was achieved along with the method of compliance. The enclosure to this letter provides the requested information.

The enclosure to this letter contains sensitive security-related information; therefore, NextEra requests that it be withheld from public disclosure pursuant to 10 CFR 2.390.

This letter makes no new commitments or changes to existing commitments.

If you have any questions related to this letter, please contact Mr. Michael Ossing, Licensing Manager at (603) 773-7512.

Sincerely,

NextEra Energy Seabrook, LLC

A handwritten signature in black ink, appearing to read "Dean Curtland", written over a horizontal line.

Dean Curtland  
Site Vice President

---

NextEra Energy Seabrook, LLC, P.O. Box 300, Lafayette Road, Seabrook, NH 03874

**Enclosure contains security-related information to be withheld under 10 CFR 2.390.  
Upon removal of the Enclosure, this letter is decontrolled.**

IE02

**Security-Related Information - Withhold Under 10 CFR 2.390**

Enclosure

cc: D. Dorman, NRC Region I Administrator  
J. Lamb, NRC Project Manager, Project Directorate 1-2  
P. Cataldo, NRC Senior Resident Inspector

**Enclosure contains security-related information to be withheld under 10 CFR 2.390.  
Upon removal of the Enclosure, this letter is decontrolled.**