

Central File

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

USNRC REGION II
ATLANTA, GEORGIA

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION


January 14, 1981

31 JAN 19 4:41

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: RII:JPO
50-269, -270, -287
IE Bulletin 80-21



Dear Sir:

Concerning the subject Bulletin, Duke Power Company has determined that no active safety-related valves at Oconee Nuclear Station have valve parts cast by Malcolm Foundry Company, Inc. In making the determination, procurement documents were reviewed or valve manufacturers were contacted for all active valves in system classes A, B, C, D, or F which were either transferred from other projects or purchased directly for Oconee.

Duke Power considers that this letter, in conjunction with my letter of December 5, 1980 which provided a preliminary response, completes the response to Bulletin 80-21 for Oconee and that no further action is required.

Very truly yours,

William O. Parker, Jr.

FTP:scs

cc: Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Division of Reactor Construction Inspection
Washington, D. C. 20555

8102030 064

Q