

**1. Project Information**

Project Name:	GKP	Date:	12/17/2013
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Mowing of firebreak trails
2.	
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2.						
3.						

5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2.				
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Cold weather related slips, trips and falls
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Lead /SSHP	Angel "Chico" Reyes		Tidewater
SRSL			



1. Personnel

[illegible]



1. Project Information

Project Name:	GKP	Date:	1/2/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Mowing Area 4
2.	
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2.						
3.						

5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2.				
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Pressurized systems (hydraulic)
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Lead /SSHP	Angel "Chico" Reyes		Tidewater
SRSL			

Page 1 of 1

**1. Project Information**

Project Name:	GKP	Date:	1/3/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police:	718-338-3988	Fire:	911	Ambulance:		Other:	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Mowing Area 11
2.	
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2.						
3.						

5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2.				
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Hidden Hazards
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Lead /SSHP	Angel "Chico" Reyes		Tidewater
SRSL			



1. Personnel

Name	Trade	On-Site	Number	Hours	Cum Hours	Employer	Description of Work
Adolfo Matus	Sr RCT	x				Tidewater	
Jeff Vance	Project Manager	x				Brightfields	
Dan Hartnett	Enviromental Tech	X				Brightfields	
Andre Owens	Jr HPT	X				Tidewater	
Harry P. Obregon	Jr HPT	X				Tidewater	

**1. Project Information**

Project Name:	GKP	Date:	1/4/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police:	718-338-3988	Fire:	911	Ambulance:		Other:	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Mowing Area 11 and area 3.
2.	
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2.						
3.						

5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2.				
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Hypothermia
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Lead /SSHP.	Angel "Chico" Reyes		Tidewater
SRSL			

[illegible]

**1. Project Information**

Project Name:	GKP	Date:	1/6/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Communication (primary and secondary)
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater



1. Personnel

[illegible]

**1. Project Information**

Project Name:	GKP	Date:	1/7/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Compressed gas cylinders
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater

Daily Safety Toolbox Meeting Form

**1. Project Information**

Project Name:	GKP	Date:	1/8/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police:	718-338-3988	Fire:	911	Ambulance:		Other:	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Foot protection
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater



1. Personnel

[illegible]

**1. Project Information**

Project Name:	GKP	Date:	1/9/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police:	718-338-3988	Fire:	911	Ambulance:		Other:	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Back protection
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater



1. Personnel

Name	Trade	On-Site	Number	Hours	Cum Hours	Employer	Description of Work
Adolfo Matus	Sr RCT	x				Tidewater	
Jeff Vance	Project Manager	x				Brightfields	
Dan Hartnett	Enviromental Tech	X				Brightfields	
Andre Owens	Jr HPT	X				Tidewater	
Harry P. Obregon	Jr HPT	X				Tidewater	



1. Project Information

Project Name:	GKP	Date:	1/10/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday:	Hand protection (gloves)
Questions/Feedback:	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater



1. Personnel

Name	Trade	On-Site	Number	Hours	Cum Hours	Employer	Description of Work
Adolfo Matus	Sr RCT	x				Tidewater	
Darnel Pratt	Operator	X				Brightfields	
Dan Hartnett	Enviromental Tech	X				Brightfields	
Andre Owens	Jr HPT	X				Tidewater	
Harry P. Obregon	Jr HPT	X				Tidewater	

**1. Project Information**

Project Name:	GKP	Date:	1/13/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Cyber security
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater



1. Personnel

Name	Trade	On-Site	Number	Hours	Cum Hours	Employer	Description of Work
Adolfo Matus	Sr RCT	x				Tidewater	
Darnel Pratt	Operator	X				Brightfields	
Dan Hartnett	Enviromental Tech	X				Brightfields	
Andre Owens	Jr HPT	X				Tidewater	
Harry P. Obregon	Jr HPT	X				Tidewater	

**1. Project Information**

Project Name:	GKP	Date:	1/14/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Public relations
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater



1. Personnel

Name	Trade	On-Site	Number	Hours	Cum Hours	Employer	Description of Work
Adolfo Matus	Sr RCT	x				Tidewater	
Darnel Pratt	Operator	X				Brightfields	
Dan Hartnett	Enviromental Tech	X				Brightfields	
Andre Owens	Jr HPT	X				Tidewater	
Harry P. Obregon	Jr HPT	X				Tidewater	

**1. Project Information**

Project Name:	GKP	Date:	1/15/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2.						
3.						


5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2.				
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Hypothermia
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater



1. Personnel

Name	Trade	On-Site	Number	Hours	Cum Hours	Employer	Description of Work
Adolfo Matus	Sr RCT	x				Tidewater	
Darnel Pratt	Operator	X				Brightfields	
Dan Hartnett	Enviromental Tech	X				Brightfields	
Andre Owens	Jr HPT	X				Tidewater	
Harry P. Obregon	Jr HPT	X				Tidewater	

**1. Project Information**

Project Name:	GKP	Date:	1/16/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2.						
3.						


5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2.				
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Deer and wildlife hazards
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater



1. Personnel

Name	Trade	On Site	Number	Hours	Cum Hours	Employer	Description of Work
Adolfo Matus	Sr RCT	x				Tidewater	
Darnel Pratt	Operator	X				Brightfields	
Dan Hartnett	Enviromental Tech	X				Brightfields	
Andre Owens	Jr HPT	X				Tidewater	
Harry P. Obregon	Jr HPT	X				Tidewater	

**1. Project Information**

Project Name:	GKP	Date:	1/17/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						


5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Deer and wildlife hazards
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater



1. Personnel

Name	Trade	On-Site	Number	Hours	Cum Hours	Employer	Description of Work
Adolfo Matus	Sr RCT	x				Tidewater	
Darnel Pratt	Operator	X				Brightfields	
Dan Hartnett	Enviromental Tech	X				Brightfields	
Andre Owens	Jr HPT	X				Tidewater	
Harry P. Obregon	Jr HPT	X				Tidewater	


1. Project Information

Project Name:	GKP	Date:	1/20/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police:	718-338-3988	Fire:	911	Ambulance:		Other:	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Deer and wildlife hazards
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater



1. Personnel

Name	Trade	On-Site	Number	Hours	Cum Hours	Employer	Description of Work
Adolfo Matus	Sr RCT	x				Tidewater	
Darnel Pratt	Operator	X				Brightfields	
Dan Hartnett	Enviromental Tech	X				Brightfields	
Andre Owens	Jr HPT	X				Tidewater	
Harry P. Obregon	Jr HPT	X				Tidewater	
Jeff Vance	Project Manager	x				Brightfields	
Clif Gray	Project Manager	x				Tidewater	

**1. Project Information**

Project Name:	GKP	Date:	1/21/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Slips, Trips and falling trees
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater

**1. Project Information**

Project Name:	GKP	Date:	1/22/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police:	718-338-3988	Fire:	911	Ambulance:		Other:	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Rotating Equipment
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater



1. Personnel

[illegible]

**1. Project Information**

Project Name:	GKP	Date:	1/23/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Winter driving conditions (on and off-site)
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater

[illegible]

**1. Project Information**

Project Name:	GKP	Date:	1/24/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police:	718-338-3988	Fire:	911	Ambulance:		Other:	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Correct PPE
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater



1. Personnel

Name	Trade	On-Site	Number	Hours	Cum Hours	Employer	Description of Work
Adolfo Matus	Sr RCT	x				Tidewater	
Darnel Pratt	Operator	X				Brightfields	
Dan Hartnett	Enviromental Tech	X				Brightfields	
Andre Owens	Jr HPT	X				Tidewater	
Harry P. Obregon	Jr HPT	X				Tidewater	

**1. Project Information**

Project Name:	GKP	Date:	1/27/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police:	718-338-3988	Fire:	911	Ambulance:		Other:	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Hidden Hazards due to weather (snow and ice)
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater



1. Personnel

Name	Trade	On-Site	Number	Hours	Cum Hours	Employer	Description of Work
Adolfo Matus	Sr RCT	x				Tidewater	
Darnel Pratt	Operator	X				Brightfields	
Dan Hartnett	Enviromental Tech	X				Brightfields	
Andre Owens	Jr HPT	X				Tidewater	
Harry P. Obregon	Jr HPT	X				Tidewater	

**1. Project Information**

Project Name:	GKP	Date:	1/28/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police:	718-338-3988	Fire:	911	Ambulance:		Other:	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Hearing protection
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater



1. Personnel

Name	Trade	On Site	Number	Hours	Cum Hours	Employer	Description of Work
Adolfo Matus	Sr RCT	x				Tidewater	
Darnel Pratt	Operator	X				Brightfields	
Dan Hartnett	Enviromental Tech	X				Brightfields	
Andre Owens	Jr HPT	X				Tidewater	
Harry P. Obregon	Jr HPT	X				Tidewater	

1. Project Information

Project Name:	GKP	Date:	1/29/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Fueling fleet vehicles
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater

Page 1 of 1



1. Project Information

Project Name	GKP	Date	1/30/2014
Project No.	N303	Location	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						

5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Off road vehicle safety
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater

Daily Safety Toolbox Meeting Form

**1. Project Information**

Project Name:	GKP	Date:	1/31/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Signage
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater

[illegible]



1. Project Information

Project Name	GKP	Date	2/3/2014
Project No.	N303	Location	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Area 9 tree removal
2. GWS	Area 4 surveys
3. GWS	Area 11 surveys

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Hazard Identification
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater





1. Project Information

Project Name:	GKP	Date:	2/4/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police:	718-338-3988	Fire:	911	Ambulance:		Other:	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Area 9 tree removal
2. GWS	Area 4 surveys
3. GWS	Area 11

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Ergonomics
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater



**1. Project Information**

Project Name:	GKP	Date:	3/3/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 11 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Warming weather
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Shane Reese		Tidewater
SSHO/CQM	Shane Reese		Tidewater

**1. Project Information**

Project Name:	GKP	Date:	3/4/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police:	718-338-3988	Fire:	911	Ambulance:		Other:	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 5 surveys
3. GWS	Area 11 surveys

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Ice
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Shane Reese		Tidewater
SSHO/CQM	Shane Reese		Tidewater

**1. Project Information**

Project Name:	GKP	Date:	3/5/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 5 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Ice slips trips falls
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Shane Reese		Tidewater
SSHO/CQM	Shane Reese		Tidewater

**1. Project Information**

Project Name:	GKP	Date:	3/6/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 5 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Warming weather
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Shane Reese		Tidewater
SSHO/CQM	Shane Reese		Tidewater



1. Project Information

Project Name:	GKP	Date:	3/7/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police:	718-338-3988	Fire:	911	Ambulance:		Other:	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 5 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Hydration with the weather warming and proper ppe
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Shane Reese		Tidewater
SSHO/CQM	Shane Reese		Tidewater

**1. Project Information**

Project Name:	GKP	Date:	3/10/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 8 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Fauna / flora hazards
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater



3/10/14

[illegible]

**1. Project Information**

Project Name:	GKP	Date:	3/11/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 8 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						


5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Trip hazards
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
SRSO	Bennie Cole		Tidewater
SSHO/CQM	Shane Reese		Tidewater

**1. Project Information**

Project Name:	GKP	Date:	3/12/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 8 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						


5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Pipeline obstructions
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
SRSO	Bennie Cole		Tidewater
SSHO/CQM	Shane Reese		Tidewater

**1. Project Information**

Project Name:	GKP	Date:	3/13/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police:	718-338-3988	Fire:	911	Ambulance:		Other:	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 8 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						


5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Communication in remote areas
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
SRSO	Bennie Cole		Tidewater
SSHO/CQM	Shane Reese		Tidewater

**1. Project Information**

Project Name:	GKP	Date:	3/14/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 8 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						


5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Traffic on site
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
SRSO	Bennie Cole		Tidewater
SSHO/CQM	Shane Reese		Tidewater



1. Personnel

[illegible]

**1. Project Information**

Project Name:	GKP	Date:	3/17/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 6 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						


5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Open wells in Area 6
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
SRSO	Bennie Cole		Tidewater
SSHO/CQM	Shane Reese		Tidewater

**1. Project Information**

Project Name:	GKP	Date:	3/18/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 6 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						


5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Open wells in Area 6
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
SRSO	Bennie Cole		Tidewater
SSHO/CQM	Shane Reese		Tidewater



1. Project Information

Project Name:	GKP	Date:	3/19/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police:	718-338-3988	Fire:	911	Ambulance:		Other:	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 6 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						


5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Open wells in Area 6
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
SRSO	Bennie Cole		Tidewater
SSHO/CQM	Shane Reese		Tidewater

**1. Project Information**

Project Name:	GKP	Date:	3/20/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 6 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						


5. Engineering Controls


Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Open wells in Area 6
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
SRSO	Bennie Cole		Tidewater
SSHO/CQM	Shane Reese		Tidewater



3/20/14

[illegible]

**1. Project Information**

Project Name:	GKP	Date:	3/21/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police:	718-338-3988	Fire:	911	Ambulance:		Other:	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 6 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						


5. Engineering Controls


Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday:	Open wells in Area 6
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
SRSO	Bennie Cole		Tidewater
SSHO/CQM	Shane Reese		Tidewater



3/21/14

[illegible]

**1. Project Information**

Project Name:	GKP	Date:	3/24/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 6 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						


5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Open wells in Area 6
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
SRSO	Bennie Cole		Tidewater
SSHO/CQM	Shane Reese		Tidewater

**1. Project Information**

Project Name:	GKP	Date:	3/25/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 6 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						

5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Open wells in Area 6
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
SRSO	Bennie Cole		Tidewater
SSHO/CQM	Shane Reese		Tidewater

**1. Project Information**

Project Name:	GKP	Date:	3/26/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police:	718-338-3988	Fire:	911	Ambulance:		Other:	Safety 347-850-5025
Hospital:	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 6 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						


5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday:	Open wells in Area 6
Questions/Feedback:	

7. Meeting Presenters

Position	Print Name	Signature	Company
SRSO	Bennie Cole		Tidewater
SSHO/CQM	Shane Reese		Tidewater

1. Project Information

Project Name:	GKP	Date:	3/27/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 6 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						


5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Open wells in Area 6
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
SRSO	Bennie Cole		Tidewater
SSHO/CQM	Shane Reese		Tidewater

**1. Project Information**

Project Name:	GKP	Date:	3/28/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 10 surveys
3.	

4. Task Hazard

Task	ISA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						


5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Poison Ivy/Poison Oak
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
SRSO	Bennie Cole		Tidewater
SSHO/CQM	Shane Reese		Tidewater

**1. Project Information**

Project Name:	GKP	Date:	3/31/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 10 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						


5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Poison Ivy/Poison Oak
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
SRSO	Bennie Cole		Tidewater
SSHO/CQM	Shane Reese		Tidewater



1. Personnel

[illegible]



1. Personnel

[illegible]



3/3/14

1. Personnel

[illegible]



1. Personnel

[illegible]



3/14/14

1. Personnel

[illegible]



1. Personnel

[illegible]



Daily Safety Toolbox Meeting

1. Personnel

2/25/14

Daily Safety Toolbox Meeting Form



ENZYME: 1.3.4.11, EC: 1.3.4.11, NAME: 1.3.4.11

2/26/14

1. Personnel

[illegible]


1. Project Information

Project Name:	GKP	Date:	1/17/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2. GWS	Yes	TBD	No	Yes	No	No
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2. Surveys	Std. with reflective vest.	N/A	N/A	N/A
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Deer and wildlife hazards <i>MSL</i> <i>Discussed near miss from 1-16-14 (NaI 3L3)</i>
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater

NEAR MISS REPORT FORM

A near miss is an incident or potential hazard that has not caused personal injury to an employee. Near miss situations could arise from equipment failure, unsafe working conditions, and unsafe employee behavior. It is the responsibility of all employees to report any near miss incidents or accidents immediately using this form.

Location of near miss incident: Great Kills park Staten Island, NY

Date of incident: 1/16/14

Time of incident: 15:00

Please check all conditions that apply

- ☐ Unsafe Equipment
☐ Unsafe Behavior

- ☒ Improper use of equipment
☐ Unsafe Working Conditions

Description of Incident or Potential Hazard: During Scanning process hanging vines impeded path forward. A machete was used to clear vines in order to progress. Both the GPS and Ludlum 44-20 units were held in left hand and machete in right. The machete was swinging at vine which happened to be dried and hollow. The machete passed through the vine and struck the Ludlum 44-20 piercing the case.

Employee Signature (optional) Harry P. O'Leary Date 1/16/14

NEAR MISS INVESTIGATION

Description of the near miss incident SAME AS ABOVE

Corrective actions taken Next day safety topic and safety meeting tailored to topic of machete safety

Completed by (print name) Shane Reese Signature [Signature]
Title SSTO / CQM Date 1/16/14

Management _____ Date _____

**1. Project Information**

Project Name:	GKP	Date:	1/16/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2.						
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2.				
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Deer and wildlife hazards
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater

TOOLBOXTOPICS.COM

Company Name _____ Job Name _____ Date _____

Oh Deer! – Driving Safely in Deer Country

In recent years, deer-vehicle collisions (DVCs) have resulted in over 100 motorist deaths annually. Thousands of DVCs result in damage to vehicles and minor to moderate injury each year, costing vehicle owners and insurance companies millions of dollars each year. The escalating numbers of deer and resulting DVCs are due in part to successive mild winters in most parts of the United States, the rapid expansion of agricultural lands, and the increased road access to traditional deer habitat.

When driving through areas that deer inhabit, it is important to take precautions to avoid a collision and prevent injury and property damage. By knowing periods of deer activity, and their habits and habitat and what to do when you encounter deer on the road, you can avoid a dangerous situation.

Deer are on the move year-round, but their travels peak in spring and summer. You will encounter deer feeding in roadside ditches in spring, looking for freshly sprouted plants like forbs and grasses to help them recover from the long winter. Deer will also feed throughout the summer to prepare for mating in the fall and to build up reserves for the oncoming cold seasons. Be alert at these times of year for increased deer activity.

Deer are also most active in low-light hours. Morning and evening, while travelling to and from work, is when many people encounter deer. Night travel also frequently puts motorists in contact with deer, and with the reduced visibility, deer are harder to see.

Pay specific attention to the roadsides when driving through agricultural and forested areas; don't rely on traditional deer crossing signs, as deer are found nearly everywhere. Deer will make split-second decisions to cross the road, and you must be able to react. In constricted areas like two-lane forest roads, you should be on the lookout for deer to avoid a DVC.

If you see one deer cross the road, expect others to be right behind it. Deer usually travel in small groups throughout most of the year. It is a good idea to use your high-beam headlights when possible to see deer in advance as you travel at night. Drive fully awake and alert, free from alcohol or medications which cause drowsiness and distractions such as cell phones – keep your focus on the road and the ditches alongside it. Drive slower than the speed limit if deer are present and adjust for fog, rain or snow.

When a DVC is unavoidable, do not swerve wildly away from the deer! Slow down as rapidly as possible by applying pressure to the brakes. In most cases, it is better to hit the deer and damage your vehicle than it is to swerve and leave the road or collide with traffic in the oncoming lane. Many fatalities and serious injuries resulting from DVCs happen when cars leave the road and roll over, or strike trees and other objects after the driver swerved and lost control.

Keep these facts in mind to prevent property damage, injury and even death, whenever your travels take you through deer country.

Thanks to N. Simonson

Safety
Recommendations: _____

Job Specific
Topics: _____

M.S.D.S
Reviewed: _____

Attended By: _____

**1. Project Information**

Project Name:	GKP	Date:	1/15/2014
Project No.:	N303	Location:	Great Kills Park

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance		Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Brush Clearing	Location to be determined as needed
2. GWS	Area 1 surveys
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Brush Clearing	Yes	No	No	Yes	No	No
2.						
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Brush Clearing	Std. with reflective vest.	N/A	N/A	N/A
2.				
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Cell phone use
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Field Manager	Angel "Chico" Reyes		Tidewater
SSHO/CQM	Shane Reese		Tidewater

TOOLBOXTOPICS.COM

Company Name _____ Job Name _____
Date _____

CELL PHONES

Talking to friends and relatives on the phone can be a very pleasant part of our day. Depending on what we are discussing, it can also be very upsetting. We could be discussing last night's football game and the winning or losing point, scheduling a doctor's appointment, having a fight with a girlfriend, checking on a sick parent, thinking, planning, emotions running high all with one hand on the telephone. This is okay if we are just sitting on the living room sofa; however, it is not okay if you are on a jobsite, **ESPECIALLY IF YOU ARE WORKING ON A HIGHWAY**. While working out in the field, talking on the phone is not appropriate. Make no mistake about it; **IT IS DANGEROUS!**

Working on or near streets and highways requires your constant awareness for the safety of motorists, pedestrians and workers. Our full attention and all of our physical capabilities should be focused on what we are doing if we expect to perform our job in a safe manner. An injury or loss of life is a high price to pay because we didn't want to miss a phone call.

For this reason, personal cell phones are not allowed on the jobsite without permission from your supervisor or foreman. They are to be kept with your other belongings, i.e., locked in a vehicle or left back at the motel or in your home. You are never supposed to be making or receiving calls on personal (unauthorized) cell phones while you are working.

Because cell phones have been listed as a contributing factor in vehicle accidents, all drivers (even if authorized to use a cell phone on the job) are not allowed to talk on the phone while driving. If you receive a call or it is necessary to make a call, pull off the road to a safe spot and park your vehicle.

Remember to be responsible and act SAFELY,
Janice Grimaldi

Safety

Recommendations: _____

Job Specific

Topics: _____

M.S.D.S

Reviewed: _____

Attended By:

**1. Project Information**

Project Name:	Great Kills TCRA	Date:	6/30/2014
Project No.:	N303	Location:	Great Kills Park, Staten Island, NY

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance	911	Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. <i>Source Recovery</i>	<i>Recovery and Removal of identified Source Material</i>
2.	
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. <i>Source Recovery</i>	<i>N/A</i>	<i>Y</i>	<i>N</i>	<i>Y</i>	<i>Y</i>	<i>N</i>
2.						
3.						

5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. <i>Source Recovery</i>	<i>Level D</i>	<i>N</i>	<i>N</i>	<i>Y</i>
2.				
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Project Manager	Clif Gray		TWI
SSHO	Kyle Emery	<i>[Signature]</i>	TWI


1. Project Information

Project Name:	Great Kills TCRA	Date:	6/27/2014
Project No.:	N303	Location:	Great Kills Park, Staten Island, NY

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance	911	Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Source	Drum recovery, excavation
2. Drilling	GPS
3. Gates	Install

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Source	Yes	Yes	No	Yes	Yes	Yes
2. Drilling	Yes	No	No	Yes	Yes	Yes/No
3. Fencing	Yes	No	No	Yes	Yes	No

5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Source	Level D	Rad / PIC	Water	Air, dose
2. Drilling	"	None	None	None
3. Fencing	"	None	None	None

6. Discussion Topics

Lessons Learned From Previous Workday	Contamination control
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Project Manager	Clif Gray	<i>Clif Gray</i>	TWI
SSHO	Kyle Emery <i>Mike Paolo</i>	<i>Mike Paolo</i>	TWI

**1. Project Information**

Project Name:	Great Kills TCRA	Date:	7/17/2014
Project No.:	N303	Location:	Great Kills Park, Staten Island, NY

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance	911	Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1.	Source recovery
2.	Backfill & Gamma surveying
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1.	Completed	None	None	Y	Y	N
2.						
3.						

5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1.	Level D	None	None	None
2.				
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Project Manager	Clif Gray		TWI
SSHO	Mike Pawlo		TWI



Daily Safety Toolbox Meeting

[illegible]

**1. Project Information**

Project Name:	Great Kills TCRA	Date:	7/16/2014
Project No.:	N303	Location:	Great Kills Park, Staten Island, NY

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance	911	Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Source Rec.	Beach filling, IDW Samples, Small Walk overs
2.	
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Source Rec.	N/A	Y	N	Y	Y	N
2.						
3.						



5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Source Rec	Level D	Gamma Meter	N	TLID
2.				
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	
Questions/Feedback	T. Storms possible

7. Meeting Presenters

Position	Print Name	Signature	Company
Project Manager	Clif Gray		TWI
SSHO	Kyle Emery		TWI

**1. Project Information**

Project Name:	Great Kills TCRA	Date:	7/15/2014
Project No.:	N303	Location:	Great Kills Park, Staten Island, NY

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance	911	Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Source Recovery	GPSing in locations + Photo + Documentation
2.	
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Source Rec	N/A	Y	W N	N	Y	N
2.						
3.						

5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. GPS				
2. Source Recovery	Level D	GPS	N	TLD
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	N/A
Questions/Feedback	T-Storms Today

7. Meeting Presenters

Position	Print Name	Signature	Company
Project Manager	Clif Gray		TWI
SSHO	Kyle Emery		TWI



8. Personnel

[illegible]



1. Project Information

Project Name:	Great Kills TCRA	Date:	6/26/2014
Project No.:	N303	Location:	Great Kills Park, Staten Island, NY

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance	911	Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Drilling	Geoprobe
2. Source	Artifact recovery
3. Fence	Gate installation

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Drilling	Yes	No	Unknown	Yes	Yes	No
2. Source	Yes	Yes	No	Yes	Yes	Yes
3. Fence	Yes	No	No	Yes	Yes	No

5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Drilling	Level D	Rad	NA	
2. Source	Level D, FED, PRD	PRD, TLD	Lapel	TLD, PRD
3. Fence	N/A	N/A	N/A	N/A

6. Discussion Topics

Lessons Learned From Previous Workday	Limiting, safe work zones
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Project Manager	Clif Gray		TWI
SSHO	Kyle Emery Mike Paolo		TWI



8. Personnel

[illegible]



1. Project Information

Project Name:	Great Kills TCRA	Date:	6/25/2014
Project No.:	N303	Location:	Great Kills Park, Staten Island, NY

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance	911	Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Drilling	Eastern boundary borings
2. Source Rec	Wetland Road
3. Fencing	Gates

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Drilling	Yes	Unknown	Unknown	Yes	Yes	Yes
2. Source	Yes	Yes	Unknown	Yes	Yes	Yes
3. Fencing	Yes	No	No	Yes	No	No

5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Drilling	Level D	TEL / Rad	n/a	RAP
2. Source	Level D / RWP	TEL / Rad	Dust Control	RAP
3. Fencing	Level D	n/a	n/a	n/a

6. Discussion Topics

Lessons Learned From Previous Workday	Communications
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Project Manager	Clif Gray		TWI
SSHO	Kyle Emery Mike Pawlo		TWI


1. Project Information

Project Name:	Great Kills TCRA	Date:	6/24/2014
Project No.:	N303	Location:	Great Kills Park, Staten Island, NY

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance	911	Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Drilling	Landfill Delineation 8" ID
2. Source Rec	Excavate hot spot
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Drilling	Yes	Unknown	Unknown	Yes	Yes	Yes
2. Source	Yes	Yes	Unknown	Yes	Yes	Yes
3.						

5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Drilling	Level D	Rad	No	Yes
2. Source	Level D	Rad	Yes	Yes
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Safe working zones person wry
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Project Manager	Clif Gray		TWI
SSHO	Kyle Emery Mike Paulo		TWI



1. Project Information

Project Name:	Great Kills TCRA	Date:	6/23/2014
Project No.:	N303	Location:	Great Kills Park, Staten Island, NY

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance	911	Other	Safety 347-850-5025 908-797-6750
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Drilling	Location Setting
2. Source Rec	Removal
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Drilling	Yes	Unknown	Unknown	Yes	Yes	Yes
2. Source Rec	Yes	Yes	Unknown	Yes	Yes	DWP
3.						

5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Drilling	Tyvek, Gloves	RAD	N/A	RAD
2. Source	"	RAD "Air"	N/A Water	Air / dose
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Project Manager	Clif Gray		TWI
SSHO	Kyle Emery		TWI



1. Project Information

Project Name:	Great Kills TCRA	Date:	6/22/2014
Project No.:	N303	Location:	Great Kills Park, Staten Island, NY

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance	911	Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Source Rec	Locate and clear brush
2.	
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Source Rec	Yes	Yes	Unknown	Yes	Yes	No
2.						
3.						

5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Source Rec	Yes	Rad. monitor	no	Yes
2.				
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	Safe zone for brush cutting
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Project Manager	Clif Gray		TWI
SSHO / RSO	Kyle Emery Bennie Cole		TWI 514



8. Personnel

Page 2 of 2



1. Project Information

Project Name:	Great Kills TCRA	Date:	6/21/2014
Project No.:	N303	Location:	Great Kills Park, Staten Island, NY

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance	911	Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Source Recovery	Reacquisition and mowing
2.	
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Source Rec	yes	yes	unknown	yes	unknown	no
2.						
3.						

5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Source Rec	Level D	TED, Bicon	n/a	Rad.
2.				
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	not applicable
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Project Manager	Clif Gray		TWI
SSHO	Kyle Emery / Bennie Cole		TWI

**1. Project Information**

Project Name:	Great Kills TCR	Date:	6/20/14
Project No.:	N303	Location:	Great Kills Park, Staten Island, NY

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance	911	Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Mowing	Mowing to facilitate Source Recovery
2. Source Recovery	Removal of Source Material
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Mowing	N/A	N	N	Y	Y	N
2. Source Recovery	N/A	Y	N	Y	Y	N
3.						

5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Mowing	Level D	Bobcat w/ Brush Cutter	N/A	N/A
2. Source Recovery	Level D	TLD, Rod Meter	N/A	Rad Meter
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	
Questions/Feedback	

7. Meeting Presenters

Position	Print Name	Signature	Company
Project Manager	Clif Gray		TWI
SSHO	Kyle Emery		TWI



... **ADMINISTRATIVE SERVICES**

8. Personnel

[illegible]

**1. Project Information**

Project Name:	Great Kills TCR	Date:	6/19/14 <small>Click here to enter a date.</small>
Project No.:	N303	Location:	Great Kills Park, Staten Island, NY

2. Emergency Contact Numbers

Police	718-338-3988	Fire	911	Ambulance	911	Other	Safety 347-850-5025
Hospital	718-226-9000						

3. Daily Work Tasks

Task	Description
1. Mowing	Mowing of known hot spots to facilitate recovery
2. Source Recovery	Recovery of known source material
3.	

4. Task Hazard

Task	JSA Completed for Task	Radiological Hazard Present	Chemical Hazard Present	Physical Hazard Present	Biological Hazard Present	Permit Required
1. Mowing	N/A	N	N	Y	Y	N
2. Source Recovery	N/A	Y	N	Y	Y	N
3.						

5. Engineering Controls

Task	PPE Requirements	Special Equipment	Airborne Controls	Monitoring Req.
1. Mowing	Mol: Pic Level D	N	N	N/A
2. Source Recovery	Mol: Pic Level D			
3.				

6. Discussion Topics

Lessons Learned From Previous Workday	
Questions/Feedback	T. storms possible

7. Meeting Presenters

Position	Print Name	Signature	Company
Project Manager	Clif Gray		TWI
SSHO	Kyle Emery		TWI

Time Sheet.

Name	Position	Company Date	Signature
Clif Gray	PM	6/17/14	Clif Gray
Bennie Cole	RSL	6/17/14	B. Cole
Kyle Emery	SSHO	6/17/14	Kyle Emery
Harry P Obregon	tech	6/17/14	Harry P Obregon
Hans White	tech	6/17/14	Hans White
Clif Gray	PM	6/18/14	Clif Gray
Kyle Emery	SSHO	6/18/14	Kyle Emery
Bennie Cole	RSL	6/18/14	B. Cole
Harry P Obregon	tech	6/18/14	Harry P Obregon
Hans White	tech	6/18/14	Hans White
Harry P Obregon	tech	6/19/14	Harry P Obregon
Hans White	tech	6/19/14	Hans White
Kyle Emery	SSHO	6/19/14	Kyle Emery

5/01/2014

[illegible]



4/30/14

[illegible]



4/24/14

1. Personnel

[illegible]



1. Personnel

Daily Safety Toolbox Meeting Form



1. Personnel

[illegible]



1. Personnel

[illegible]