



FEB 26 2016

L-2016-044
10 CFR 50.55a

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555-00001

Re: Turkey Point Unit 3
Docket No. 50-250
Inservice Inspection Program
Owner's Activity Report (OAR-1)

Attached find the Owner's Activity Report (Form OAR-1), for Turkey Point Unit 3 Fifth Inservice Inspection Interval, First Period, Second Refueling Outage (PTN 3-28). The Form OAR-1, Owner's Activity Report, implements Code Case N-532-5.

Should there be any questions concerning this report, please contact Mr. Mitch Guth, Licensing Manager, at 305-246-6698.

Sincerely,

A handwritten signature in black ink, appearing to read "T. Summers", is written over a horizontal line.

Thomas Summers
Vice President
Turkey Point Nuclear Plant

SM

Attachment

A047
NRR

FORM OAR-1 OWNER'S ACTIVITY REPORT

Report Number: ISI-PTN3-28

Plant: Turkey Point Nuclear Power Plant Unit 3
9760 SW 344th Street
Homestead, Florida 33035

Commercial Service Date: December 14, 1972 Refueling Outage No.: PTN 3-28

Current Inspection Interval: ISI-Fifth IWE-Second

Current Inspection Period: ISI Fifth Interval-First Period and IWE Second Interval - Third Period

Edition and Addenda of Section XI applicable to the inspection plans: ISI Fifth Interval-2007
Edition with Addenda through 2008 and IWE-2001 with Addenda through 2003.

Date and Revision of Inspection Plans: ISI Fifth Interval Effective-February 22, 2014 Rev. 0 and
IWE Second Interval Effective March 3, 2009, Rev.0

Edition and Addenda of Section XI applicable to repairs and replacements, if different than the inspection plan: ASME Section XI 2007 Edition through 2008 Addenda.

Code Cases Used: As Referenced in the ISI Program Plan and Schedule

CERTIFICATE OF CONFORMANCE

I certify that (a) the statements made in this report are correct; (b) the examinations and tests meet the Inspection plan as required by the ASME Code, Section XI; and (c) the repair/replacement activities and evaluations supporting the completion of PTN3-28 conform to the requirements of Section XI.

Signed R. P. G. FURST, RUCS, President RUCS. Date 2/22/16
Owner or Owner's Designee, Title

CERTIFICATE OF INSERVICE INSPECTION

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and the State or Province of Georgia and employed by the Hartford Steam Boiler Inspection and Insurance Company of Connecticut have inspected the items described in this Owner's Activity Report, and state that, to the best of my knowledge and belief, the Owner has performed all activities represented by this report in accordance with the requirements of Section XI.

By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the repair/replacement activities and evaluation described in this report. Furthermore, neither the inspector nor his employer shall be liable in any manner for any personal injury or property damage or loss of any kind arising from or connected with this inspection.

[Signature]
Inspector's Signature

Commissions NB 14292 A.N.I GA983
National Board, State, Province and Endorsements

Date February 25, 2016

FORM OAR-1 OWNER'S ACTIVITY REPORT

TABLE 1 ITEMS WITH FLAWS OR RELEVANT CONDITIONS THAT REQUIRED EVALUATION FOR CONTINUED SERVICE		
Examination Category and Item Number	Item Description	Evaluation Description
NONE	NONE	NONE

FORM OAR-1 OWNER'S ACTIVITY REPORT

TABLE 2 ABSTRACT OF REPAIR/REPLACEMENT ACTIVITIES REQUIRED FOR CONTINUED SERVICE				
Code Class	Item Description	Description Of Work	Date Completed	Repair/Replacement Plan Number
1,2,3	Snubbers Various	Replace Snubbers and Load Pins	11/19/2015	RR40351819-01
1	Valve 3-385	Replace	11/30/2015	RR37020966-01
1	Valve CV-3-200B	Replace Bonnet Bolting	11/30/2015	RR40160997-01
1	Safety Valve RV-3-551B	Replace Bonnet Nut	11/30/2015	RR40352529-01
2	Support 8080-R-006-01	Remove indication from support	11/21/2015	RR40425245-01
2	Valve SGWL-3-025	Replace Valve	11/30/2015	RR40161364-01
2	Valve CV-3-303A	Replace bonnet bolting	11/30/2015	RR40272223-26
2	Valve CV-3-303B	Replace bonnet bolting	11/30/2015	RR40355834-26
2	Valve CV-3-303C	Replace bonnet bolting	11/30/2015	RR40355835-26

FORM OAR-1 OWNER'S ACTIVITY REPORT

TABLE 2 ABSTRACT OF REPAIR/REPLACEMENT ACTIVITIES REQUIRED FOR CONTINUED SERVICE				
Code Class	Item Description	Description Of Work	Date Completed	Repair/Replacement Plan Number
2	Relief Valve RV-3-858B	Replace Flange Bolting	11/30/2015	RR40034113-01
2	Piping near Valve 3-293C	Remove tooling marks in pipe	11/21/2015	RR40428318-01
2	Piping near Valve 3-293A	Remove Arc Strikes on piping	11/21/2015	RR40428320-01
2	Piping 3A RCP	Modify Piping during RCP modification	11/30/2015	RR40272223-21
2	Piping 3B RCP	Modify Piping during RCP modification	11/30/2015	RR40355834-18
2	Piping 3C RCP	Modify Piping during RCP modification	11/30/2015	RR40355835-18
3	Relief Valve RV-3-1412	Replace Bolting	12/04/2015	RR40419744-01
3	Relief Valve RV-3-707	Replace Valve with New	11/15/2015	RR40281615-02
3	Heat Exchanger 3E207A	Retube Heat Exchanger	2/20/2015	RR40088991-01
3	Heat Exchanger 3E207B	Retube Heat Exchanger	03/06/2015	RR40088994-01

FORM OAR-1 OWNER'S ACTIVITY REPORT

TABLE 2 ABSTRACT OF REPAIR/REPLACEMENT ACTIVITIES REQUIRED FOR CONTINUED SERVICE				
Code Class	Item Description	Description Of Work	Date Completed	Repair/Replacement Plan Number
3	Heat Exchanger 3E207C	Retube Heat Exchanger	2/07/2015	RR40088995-01
3	Valve 3-50-321	Replace Valve	07/10/2015	RR40243391-01
3	Piping FLEX CST-1	Add FLEX-Connection	11/26/2014	RR40295266-10
3	Piping FLEX CST-2	Add FLEX-Connection	9/22/2015	RR40295266-11
3	Piping FLEX SFP-1	Add FLEX-Connection	7/2/2015	RR40295266-13
3	Piping FLEX AFW-1	Add FLEX-Connection	4/11/2015	RR40295266-01
3	Piping FLEX AFW-2	Add FLEX-Connection	4/11/2015	RR40295266-02
3	Tank Manway 3T8 CST	Replace Bolting on Manway	09/26/2014	RR40295266-23
3	Piping ICW Piping	Install Temporary Cooling	8/25/2014	RR40329808-02
3	Basket Strainer BS-3-1402	Install Blind Flanges	08/22/2014	RR40329808-03

FORM OAR-1 OWNER'S ACTIVITY REPORT

TABLE 2 ABSTRACT OF REPAIR/REPLACEMENT ACTIVITIES REQUIRED FOR CONTINUED SERVICE				
Code Class	Item Description	Description Of Work	Date Completed	Repair/Replacement Plan Number
3	Basket Strainer BS-3-1403	Install Blind Flanges	08/22/2014	RR40329808-06
3	Basket Strainer BS-3-1402	Reinstall Backwash Piping	11/19/2014	RR40329808-08
3	Basket Strainer BS-3-1403	Reinstall Backwash Piping	11/19/2014	RR40329808-09
3	Piping ICW Piping	Install Temp Cooling	05/30/2015	RR40376230-11
3	Basket Strainer BS-3-1402	Install Blind Flanges	5/25/2015	RR40376230-12
3	Basket Strainer BS-3-1403	Reinstall Backwash Piping	5/26/2015	RR40376230-15
3	Piping Supports CCW Supports	CCW Supplemental Cooling Modification	8/11/2015	RR40369651-23
3	Piping CCW Piping	CCW Supplemental Cooling Modification	9/3/2015	RR40369651-57
3	Piping CCW Piping	CCW Supplemental Cooling Modification	9/3/2015	RR40369651-20