

**Open Generic Communication TACs (PA No. 115126)
Summary Report (As Of 4/30/2016)**

TAC NO.	TAC TITLE	AGE (Mon)	TAC OPENED	LEAD ORG
MF3949	RIS 'RIS 2005-29 Rev 1 Anticipated Transients That Could Develop into More Serious Events'	25.0	04/17/2014	DSS
MF4346	RIS 'Pressure Boundary Leakage'	23.0	07/02/2014	NRO
MF5565	RIS 'PCT Reporting Required by 50.46'	16.0	01/13/2015	DSS
MF5661	RIS 'Safety-Related SSCs in Service Beyond Service Life'	15.0	02/03/2015	PGCB
MF6131	RIS 'Clarification of the Requirements of 10 CFR 37.11b Specific Exemptions'	13.0	04/23/2015	PGCB
MF6195	RIS 'ASME Code Relief Request'	12.0	05/06/2015	PGCB
MF6357	RIS 'Compensatory Measures for Protective Strategy Deficiencies'	11.0	06/16/2015	PGCB
MF6496	RIS 'Containment Liner Moisture Barrier Inspection'	10.0	07/21/2015	PGCB
MF7013	RIS 'Emergency Response Organization Staffing'	6.0	10/29/2015	PGCB
MF7230	RIS 'Identifying and Reporting Human Factor Incidents Under 10 CFR 50.73'	4.0	01/13/2016	PGCB
MF7293	IN 'Impacts on Site Power Distribution from Inadequate Contractor Oversight	3.0	02/01/2016	PGCB
MF7422	IN 'Recent Issues Identified When Using Reverse Engineering Techniques in Procurement'	2.0	03/03/2016	PGCB
MF7475	RIS 'NRO New Licensing Applications'	1.0	03/17/2016	PGCB

Open Generic Communication TACs (PA No. 115126)
Summary Report (As Of 4/30/2016)

TAC NO.	TAC TITLE	AGE (Mon)	TAC OPENED	LEAD ORG
MF7539	IN 'Potential for Material Handling Events to Cause Internal Flooding'	1.0	03/29/2016	PGCB
MF7566	RIS 'Switchyard access for NRC Inspectors'	1.0	04/07/2016	PGCB
MF7568	RIS 'Design Vulnerability in Electric Power Systems'	1.0	04/08/2016	PGCB
MF7575	IN 'Faulted Circuit Breaker Connections'	.5	04/12/2016	PGCB
MF7597	RIS 'Clarifying Appropriate Methods for Resolving Errors in AP1000 Certified Design Information'	.5	04/20/2016	PGCB
MF7614	RIS 'Annual Operator Licensing'	.1	04/25/2016	PGCB