

# DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

June 12, 1980

TELEPHONE: AREA 704  
373-4083

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: Oconee Nuclear Station  
Docket Nos. 50-269, -270, -287

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-269/80-16, which is submitted pursuant to Oconee Nuclear Station Technical Specification 6.6.2.1.a(8). This report describes an inconsistency which was discovered in the analysis of a steam generator tube failure contained in the Oconee Final Safety Analysis Report. The inconsistency has been evaluated and determined to be of no significance with respect to safe operation or the health and safety of the public.

Very truly yours,

*William O. Parker, Jr.*  
William O. Parker, Jr. *By [Signature]*

SRL:scs  
Attachment

cc: Director  
Office of Management & Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. Bill Lavallee  
Nuclear Safety Analysis Center  
P. O. Box 10412  
Palo Alto, California 94303

*1002  
5,11*

*5* 8006170 523