

ACCESSION: NRC-2-0714397 DOC. DATE: 80/06/08 NOTARIZED: NO
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.
 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co.
 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co.
 AUTH. NAME: PARKER, W.O. AUTHOR AFFILIATION: Duke Power Co.
 RECIP. NAME: DENTON, H.R. RECIPIENT AFFILIATION: Office of Nuclear Reactor Regulation, Director

DOCKET #
 05000269
 05000270
05000287

SUBJECT: Refers to 800701 ltr requesting info re insp of fuel assembly hold-down springs. Reviewed concern & documented results in 800606 ltr forwarding RO 50-269/80-15 & safety evaluation. No further info required.

DISTRIBUTION CODE: A001S COPIES RECEIVED: LTR L ENCL 0 SIZE: 1
 TITLE: General Distribution for after Issuance of Operating Lic

NOTES: M. CUNNINGHAM: ALL AMENDS TO FSAR & TECH SPEC CHANGES

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL		RECIPIENT ID CODE/NAME	COPIES LTR ENCL
ACTION:	BC <u>REID, R.</u> 05	1		PM <u>FAIRTILE, M</u>	12 1
INTERNAL:	DIR, HUM FAC SPY	1		I&E	12 2
	MOORE, V. 22	1		NRC PDR	02 1
	OELD 14	1		OR ASSESS BR 19	1
	<u>REG FILE</u> 01	1			
EXTERNAL:	ACRS 20	1		LPDR	03 1
	NSIC 01	1			

JUL 15 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR 39 ENCL 0

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

July 8, 1980

TELEPHONE: AREA 704
373-4083

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Subject: Oconee Nuclear Station
Docket Nos. 50-269, -270, -287


Dear Sir:

In a letter dated July 1, 1980, the NRC Staff requested information related to the inspection of fuel assembly hold-down springs at Oconee as a result of the failures of similar hold-down springs at the Davis-Besse Unit 1 plant. Furthermore, the Staff requested a determination of the safety significance operating with broken springs in the core.

Duke Power has previously reviewed this concern and documented the results in my letter of June 6, 1980 which forwarded Licensee Event Report RO-269/80-15 to Mr. O'Reilly of Region II. Included in this report were the inspection results as well as a safety evaluation.

It is considered that this report adequately addresses the NRC questions in the July 1, 1980 letter and that no further information is required.

Very truly yours,


William O. Parker, Jr.

RLG:scs

A001
S
1/0

8007140397