

DUKE POWER COMPANY

P.O. BOX 33189

CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

85 NOV 13 AB:19
October 25, 1985

TELEPHONE
(704) 373-4531

Dr. J. Nelson Grace, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Re: Oconee Nuclear Station, Unit 3
Docket No. 50-287

Dear Dr. Grace:

By letter dated October 21, 1985, Duke Power Company submitted information concerning the Oconee Unit 3 steam generator, pursuant to Oconee Nuclear Station Technical Specification 4.17.6(a). The steam generator plugging for the current Unit 3 refueling outage was completed on August 31, 1985; however, the number of tubes removed from service was incorrect. The "A" OTSG had a total of four (4) tubes removed from service by stabilizing and/or plugging. The "B" OTSG had a total of ten (10) tubes removed from service by stabilizing and/or plugging.

Very truly yours,

H.B. Tucker
Hal B. Tucker

SGG:slb

cc: Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Ms. Helen Nicolaras
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. J. C. Bryant
NRC Resident Inspector
Oconee Nuclear Station

8511190124 851025
PDR ADDCK 05000287
P PDR

1/0
IE 01