

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8809300004 DOC. DATE: 88/09/22 NOTARIZED: NO DOCKET #
 FACIL: 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co. 05000287
 AUTH. NAME AUTHOR AFFILIATION
 TUCKER, H.B. Duke Power Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Informs of completion of steam generator plugging & repair
 for current Unit 3 outage on 880907.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: OR Submittal: General Distribution

NOTES: AEOD/Ornstein:lcy. 05000287

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD2-3 LA	1 0	PD2-3 PD	5 5
PASTIS, H	1 1		
INTERNAL: ACRS	6 6	ARM/DAF/LFMB	1 0
NRR/DEST/ADS 7E	1 1	NRR/DEST/CEB 8H	1 1
NRR/DEST/ESB 8D	1 1	NRR/DEST/MTB 9H	1 1
NRR/DEST/RSB 8E	1 1	NRR/DOEA/TSB 11	1 1
NRR/PMAS/ILRB12	1 1	NUDOCS-ABSTRACT	1 1
OGC/HDS2	1 0	<u>REG FILE</u> 01	1 1
RES/DSIR/EIB	1 1		
EXTERNAL: LPDR	1 1	NRC PDR	1 1
NSIC	1 1		
NOTES:	1 1		

TOTAL NUMBER OF COPIES REQUIRED: LTTR 29 ENCL 26

R
I
D
S
/
A
D
D
S

R
I
D
S
/
A
D
D
S

mem.

m/104

Duke Power Company
P.O. Box 33198
Charlotte, N.C. 28242

HAL B. Tucker
Vice President
Nuclear Production
(704)373-4531



DUKE POWER

September 22, 1988

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Subject: Oconee Nuclear Station, Unit 3
Docket No. 50-287
OTSG Tube Plugging and Repair

Gentlemen:

Pursuant to Oconee Nuclear Station Technical Specification 4.17.6(a), Duke Power Company is providing the following information concerning the Oconee Unit 3 steam generators. The steam generator plugging and repair for the current Unit 3 outage was completed on September 7, 1988. The "A" OTSG had a total of eighteen (18) tubes removed from service by plugging. The "B" OTSG had a total of four (4) tubes removed from service by plugging. In addition, one hundred fifty (150) tubes were repaired by sleeving in the "A" OTSG and ninety-seven (97) tubes were repaired by sleeving in the "B" OTSG.

Very truly yours,

Hal B. Tucker

PJN/389/mm

xc: Dr. J. Nelson Grace, Regional Administrator
U.S. Nuclear Regulatory Commission - Region II
101 Marietta Street, NW, Suite 2900
Atlanta, GA 30323

Ms. Helen Pastis
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. P.H. Skinner
NRC Resident Inspector
Oconee Nuclear Station

8809300004 880922
PDR ADDCK 05000287
P PNU

A001
1/0