

**Open Generic Communication TACs (PA No. 115126)  
Summary Report (As Of 5/31/2016)**

<b>TAC NO.</b>	<b>TAC TITLE</b>	<b>AGE (Mon)</b>	<b>TAC OPENED</b>	<b>LEAD ORG</b>
MF3949	RIS 'RIS 2005-29 Rev 1 Anticipated Transients That Could Develop into More Serious Events'	26.0	04/17/2014	DSS
MF4346	RIS 'Pressure Boundary Leakage'	24.0	07/02/2014	NRO
MF5661	RIS 'Safety-Related SSCs in Service Beyond Service Life'	16.0	02/03/2015	PGCB
MF6131	RIS 'Clarification of the Requirements of 10 CFR 37.11b Specific Exemptions'	14.0	04/23/2015	PGCB
MF6357	RIS 'Compensatory Measures for Protective Strategy Deficiencies'	12.0	06/16/2015	PGCB
MF7013	RIS 'Emergency Response Organization Staffing'	7.0	10/29/2015	PGCB
MF7230	RIS 'Identifying and Reporting Human Factor Incidents Under 10 CFR 50.73'	5.0	01/13/2016	PGCB
MF7293	IN 'Impacts on Site Power Distribution from Inadequate Contractor Oversight	4.0	02/01/2016	PGCB
MF7422	IN 'Recent Issues Identified When Using Reverse Engineering Techniques in Procurement'	3.0	03/03/2016	PGCB
MF7475	RIS 'NRO New Licensing Applications'	2.0	03/17/2016	PGCB
MF7539	IN 'Potential for Material Handling Events to Cause Internal Flooding'	2.0	03/29/2016	PGCB
MF7566	RIS 'Switchyard access for NRC Inspectors'	2.0	04/07/2016	PGCB
MF7568	RIS 'Design Vulnerability in Electric Power Systems'	2.0	04/08/2016	PGCB

**Open Generic Communication TACs (PA No. 115126)**  
**Summary Report (As Of 5/31/2016)**

<b>TAC NO.</b>	<b>TAC TITLE</b>	<b>AGE (Mon)</b>	<b>TAC OPENED</b>	<b>LEAD ORG</b>
MF7575	IN 'Faulted Circuit Breaker Connections'	1.0	04/12/2016	PGCB
MF7597	RIS 'Clarifying Appropriate Methods for Resolving Errors in AP1000 Certified Design Information'	1.0	04/20/2016	PGCB
MF7614	RIS 'Annual Operator Licensing'	1.0	04/25/2016	PGCB