



ASCO Valve, Inc.
1561 Columbia Highway
Aiken, SC 29801
USA

T (803) 641-9200
F (803) 641-9290
www.asconumatics.com

May 17, 2016

Richard P. McIntyre, Acting Chief
Quality Assurance Vendor Inspection Branch 2
Division of Construction Inspection
and Operational Programs
Office of New Reactors

Ref: NRC Inspection Report No. 999010542016-201, Extension Request

Dear Mr. McIntyre,

ASCO has assembled a team to review the subject inspection report and prepare a response. The nature of the finding detailed in the report will require additional time for ASCO to thoroughly research on the extent of condition, as well as the corrective/preventive actions ASCO will need to implement. In addition, The Nuclear Independent Assessment Committee (NIAC) is currently performing their annual audit of ASCO. They visited the Aiken facility from May 3rd through May 5th, and are currently in the Florham Park facility from May 16th through May 18th. This activity has consumed many of the resources ASCO needs to effectively complete our response to the NRC inspection report.

We respectfully request an extension of 30 days to complete our response. This extension would move the due date for response from May 20 to June 20. Thank you in advance for your consideration of this request.

Sincerely,

Michael G. Lenio
Director of Quality Assurance
ASCO Valve, Inc.

6/1/16
original.
Sumit completed.
to

IE09
NRO