

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:
Rink International, LLC
1277 Gold Hill Road
Princeton, ID 83857
Location Inspected: same as above
REPORT NO: 030-36268/2016-001

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission - Region IV
1600 East Lamar Boulevard
Arlington, Texas 76011-4511

3. DOCKET NUMBER
030-36268

4. LICENSE NUMBER
11-27756-01

5. DATES OF INSPECTION
September 7, 2016

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
2. Previous violation(s) closed.
3. The violations(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title

Printed Name

Signature

Date

LICENSEE'S
REPRESENTATIVE

NRC INSPECTOR Janine F. Katanic, PhD, CHP

BRANCH CHIEF Ray L. Kellar, P.E.

Janine F. Katanic
Ray L. Kellar

9/28/2016
10/18/16

Katanic, Janine

From: rinkint@aol.com
Sent: Thursday, September 29, 2016 6:54 PM
To: Katanic, Janine
Cc: Torres, RobertoJ
Subject: [External_Sender] Re: NRC Inspection Report- Rink International, LLC

Dear Dr. Katanic,

Ok, I will do so. Thank you very much for your guidance. I will be in touch.

Sincerely,

Karl Rink

-----Original Message-----

From: Katanic, Janine <Janine.Katanic@nrc.gov>
To: rinkint <rinkint@aol.com>
Cc: Torres, RobertoJ <roberto.torres@nrc.gov>
Sent: Wed, Sep 28, 2016 8:54 am
Subject: NRC Inspection Report- Rink International, LLC
Dr. Rink,

Thanks for updating us on the progress that you have made in upgrading your facility. As discussed during the inspection, when your remodel is complete, please send us an amendment request with the as-built drawings so that they may be incorporated into your license. These drawings should include a configuration of the equipment (i.e. Radiflo, counting station) in the work area. You should also submit a schematic of the ventilation system. This schematic should include the entire ventilation system, specifically all of the components that are incorporated into the design (i.e. extra chamber for decay, container for storage of waste oil/gaskets). You should specify the installed stack height and determine the flow rate for the system with all of the installed components. In your submission, you can include photographs, as appropriate. Once you have the ventilation system set up and operable, and have determined the necessary information, you can re-do your calculations, correcting the identified errors. After you establish the downwind concentration, you can take that information to its next logical step and determine the radiation dose downwind.

Attached is the NRC Inspection Report documenting that there were no violations identified during the inspection. Please respond by email to confirm receipt.

Regards,
Janine

Janine F. Katanic, PhD, CHP
Senior Health Physicist
US Nuclear Regulatory Commission
Region IV
Division of Nuclear Materials Safety
office: 817-200-1151
email: Janine.Katanic@nrc.gov